## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION



## LAND CORNER RECORD

T. 24 N.R. 8 W

		Missaukee	COUNTY
DESCRIPTION OF CORNER _	1/4 corner common to Section	ons 10-15	<del></del>
CORNER MONUMENT	Set 1" pipe with 4" alumin	и сар	<del>_</del>
DATE MONUMENT PLACED AND	WITHESSED <u>5-24-67</u>		
WITHESSES TO CORNER			
N	16" W. Oek	N 46 E	65.21
16	16" Tw. W. Oak	S 31 E	68.71
CINCLE CORNER REGISTERED	AND		

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored during survey in this area. Found Fargo pipe at corner. Their record claims to have recovered this corner from U.S. evidence, and appears to be best available evidence of proper location for corner.

SURVEYOR'S SEAL

SIGNED COURTES LAND SURVEYOR \$10068 DATE 6-15-67