

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Missaukee
(County)
Located In
Corner Code #
1. Public Land Survey
2. Property Controlling in Section
3. Miscellaneous Property in Section
4. Lot No:
5. Private Claims:

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M). Contains numerical data for land surveying.

I, Joshua R. Davidson, in a field survey on November 7, 2013 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1 - W 1/16 corner on North line of section 2
4 - NW 1/16 corner section 25
1983 - Unrecorded Survey, File No. 8314 - Robert Mitchell, PS #28417 - set 1/2" rerod.
2014-00525 L: L-7 P: 2341 LCORNER
02/14/2014 09:09:33 AM Page 1 of 1
Carolyn Flore County Recorder, Missaukee County MI

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

1 - W 1/16 corner on North line of section 2
4 - NW 1/16 corner section 25
Found 1/2" rebar and cap #28417. Accepted found rebar and cap as the best available evidence of the position of the corner and replaced it with a stamped 2" aluminum cap on 5/8" x 34" rebar.
Found 1/2" rebar and cap #28417 and accessories #1, #2(dead) fitting position. Accepted found rebar and cap as the best available evidence of the position of the corner and replaced it with a stamped 2" aluminum cap on 5/8" x 34" rebar.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1 - a stamped 2" aluminum cap on 5/8" x 34" rebar
4 - a stamped 2" aluminum cap on 5/8" rebar
N66°E 13.73' to set nail & tag in NW. side 9" R. Pine
S20°E 28.73' to set nail & tag in W. side 12" R. Pine
N65°W 41.70' to set nail & tag is SW. side 12" R. Pine
N04°W 35.54' to set nail & tag in W. side 9" R. Pine
Set blue post with location tag 1' East
N18°E 32.73' to set nail & tag in W. side 9" Oak
N77°E 80.85' to set nail & tag in NW. side 12" R. Pine
S36°E 81.83' to set nail & tag in NE. side power pole
N80°W 17.30' to set nail & tag in S. side 4" Oak
Set blue post with location tag 1' Northeast

Signed by:
Surveyor's Michigan License No.: 46659

Date: 2/14/2014

