## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

	Timig Fraquitation of Fice 1-4, What	
For Corners In: Missaukee (County)	_ Located In Corner Code #	
1. Public Land Survey	T 24N R 8W C6	
2. Property Controlling in Section S	T R T R	
3. Miscellaneous Property in Section S S	Τ R	Register of Deeds Stamp & File Number
4. Lot No: Reco	orded Plat:	ABCDEFGH!JK&M
5. Private Claims:		1
I, Craig W. McVean, in a field survey on May 5, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:		4 7 8 9 10 11 12 5 6 18 17 15 15 14 13 7 8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.		10 30 29 28 27 28 25
		13
A. Description of original monument and accessories and/or subsequent restoration:  C6 - 1853 - GLO - T. Whelpley - Set 1/4 Post  1) Manle 4" N60° 5 34 I		
1) Maple 4" N69°E 34 L. 2) W. Oak 10" S50½°W 23	, <b>L.</b>	CRAIG W. MCVEAN PROFESSIONAL SURVEYOR NO. 39088
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:		
<u>C6</u> – ¼ Corner common to Sections 17 & 18, T24N, R8W – No GLO evidence was found. Set DNR Monument by single proportion between 'C5' and 'C7'. Grid distance N and S is 2654.07' (2640' – GLO). DNR Monument accepted as a careful and faithful reestablishment of the position of the original corner.		
C. Description of monument for	corner and accessories established to perpetuate	locating the position of the corner
C6 – 4" DNR Alum. Cap on 1" x 36" long galv. iron pipe. Set Cedar post 1' North S66°E 35.60' to set N & T in SW side 11" Oak S21°W 64.83' to set N & T in W. side 6" Oak N45°W 8.21' to set N & T in SW side 6" R. Maple N5°W 100.90' to set N & T in W. side 10" W. Pine		
Signed by: Our M. M. M. Date: 12/16/2010 Surveyor's Michigan License No.: 39088		