

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Missaukee

(County)

Located In

Corner Code #

1. Public Land Survey	T	24N	R	8W	C7
	T		R		
2. Property Controlling in Section	S		T	R	
	S		T	R	
3. Miscellaneous Property in Section	S		T	R	
	S		T	R	

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Craig W. McVean, in a field survey on April 6, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

C7 - 1853 - GLO - Set Post - T. Whelpley

- 1) Beech 8" N57½°W 25 L.
- 2) Beech 6" N54½°E 20 L.
- 3) W. Pine 8" S83½°W 29 L.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C7 - Section Corner common to Sections 17, 18, 19 & 20, T24N, R8W - No conclusive GLO evidence was found. A number of large pine stumps in area and a couple of small ones. Dug from the smaller ones one 8"± and another 16"± but no evidence of stake was found. Search for line tree evidence N, S, E & W was inconclusive. Set DNR Monument by double proportion to GLO from existing corners 1 mile N, S, E & W. Corner near to Top of Hill. DNR Monument accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C7 - Stamped 4" DNR Alum. Cap on 1" x 36" galv. iron pipe.

Set Cedar post 1' South.

N52°W 32.90' to set N & T in SW side 14' Oak scribed 'XBT'

N11°W 10.72' to set N & T in W. side 22" Oak scribed 'XBT'

S66°E 24.47' to set N & T in N. side 20" W. Oak scribed 'XBT'

S27°W 27.70' to set N & T in N. side 6" R. Maple scribed 'XBT'



Signed by:

Craig W. McVean

Date:

12/16/2010

Surveyor's Michigan License No.:

39088