

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Missaukee
(County)

Located In

Corner Code #

1. Public Land Survey T 24N R 8W D7
T _____ R _____
2. Property Controlling in Section S _____ T _____ R _____
S _____ T _____ R _____
3. Miscellaneous Property in Section S _____ T _____ R _____
S _____ T _____ R _____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Craig W. McVean, in a field survey on May 4, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

D7 – 1853 – GLO – T. Whelpley – Set ¼ Post

- 1) Beech 4" N32¼°W 17 L.
- 2) Beech 6" S11½°E 23 L.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D7 – ¼ Corner common to Sections 17 & 20, T24N, R8W – No GLO evidence was found. Line tree evidence E & W was inconclusive. Set DNR Monument by single proportion between 'C7' and 'E7'. Measured grid distances E & W of 2649.32' (2640' – GLO). DNR Monument accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D7 – Stamped 4" DNR Alum. Cap on 1" x 36" long galv. iron pipe. Set Cedar post 1' East.
N53°E 16.27' to set N & T in NW side 6" Oak in clump scribed 'XBT'
N74°W 46.94' to set N & T in S. side 8" W. Pine scribed 'XBT'
S45°E 27.35' to set N & T in NE side 3" R. Maple scribed 'XBT'
S53°W 42.71' to set N & T in NW side 4" R. Maple scribed 'XBT'



Signed by:

Craig W. McVean

Date:

12/16/2010

Surveyor's Michigan License No.:

39088