

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Missaukee

(County)

Located In

Corner Code #

1. Public Land Survey
T _____ R _____
T _____ R _____
2. Property Controlling
in Section S 13 T 24N R 8W 1
S 13 T 24N R 8W 4
3. Miscellaneous
Property in Section S _____ T _____ R _____
S _____ T _____ R _____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Craig W. McVean, in a field survey on April 5, 2004 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

- 1 - CSR - E.A. Beuthien - 1914
Cedar Post - Poplar 8" N45°W 50
Poplar 8" N27°E 62
- 4 - None



B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- 1 - W 1/16 Cor. common to Sec. 12 & 13 -
No conclusive evidence of Beuthien position found.
Set 2" Alum. Cap on 5/8" x 34" iron rebar per standard
BLM procedure. Fd. a newer cedar post S45°W 6' and
fence remains to the N. are 5'± W.
- 4 - NW 1/16 Cor. Sec. 13 -
Set 2" Alum. Cap on 5/8" x 34" iron rebar per standard
BLM procedure.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- 1 - Stamped 2" Alum. Cap on 5/8" x 34" rebar -
N15°W 48.66' to set N & T in W. side 7" R. Pine
N80°E 52.52' to set N & T in N. side 16" W. Pine
S51°E 30.81' to set N & T in SW side 6" W. Pine
S42°W 46.76' to set N & T in SE side 13" W. Pine
SE 1' to set blue carsonite post w/ loc. tag
- 4 - Stamped 2" Alum. Cap on 5/8" x 34" rebar
N27°E 10.33' to set N & T in NW side 6" Cedar
N80°E 10.75' to set N & T in S. side 8" Cedar
S22°W 29.08' to set N & T in E. side 12" Cedar
N80°W 24.80' to set N & T in S. side 9" Fir
NE 1' to set blue carsonite post w/ loc. tag

Signed by:

Craig W. McVean

Date:

5/20/2004

Surveyor's Michigan License No.:

39088