

JAN 16 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Missaukee
(County)

Located In:

Corner Code #

1. Public Land Survey

T24NR 8W

G-13

T R

T R

T R

T R

2. Property Controlling in Section

S

T R

3. Miscellaneous Property in Sec

S

T R

S

T R

4. Lot No. _____, Recorded Plat

5. Private Claims

I, J. Dean Geers, in a field survey on June, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- G-13) 1838 GLO Section Post by John Brink, Deputy Surveyor; Sugar 12-N58E-20, Sugar 10-N54½W-40
G-13) 1853 GLO Subdivision by Whelpley; Sugar 18-N58E-21, Ironwood 8-N49¼W-38
G-13) 1892 Richardson Survey in Section 33, T24N, R8W; Perpetuated corner by setting a 3" square x 18" Cedar stake with 4 pieces of broken plow points, small stones and lime
G-13) 1909 Cavanagh Survey in Section 33, T24N, R8W; Telephone Pole-S60W-81, Fence Post-N2W-36
G-13) 1982 Lake State Surveying & Engineering Survey in Section 3, T23N, R8W; Liber S-2, Page 85; Found Plow Point; Power Pole-S9W-80.36, 8" Scotch Pine-S31E-76.40, 4" Scotch Pine-S37W-104.91

Continued on back

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- G-13) Section Corner common to Sections 33 and 34, T24N, R8W and Sections 3 and 4, T23N, R8W; Found Iron and Cap of record $\pm 5'$ North of East-West road centerline. This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:


- G-13) Set Missaukee County Monument on 1/2" Iron
N45W 79.52 Set Iron
S12W 79.97 Power Pole
S25E 71.70 6" Jack Pine
N55E 51.31 Set Iron

Peer Group Reviewed and Approved

Date: 10-15-97
J. Dean Geers, Missaukee Co. Representative

Signed by

Surveyor's Michigan License No.



Date 10-22-97

A. (Continued)

- G-13) 1986 Wilcox LCRC, Liber 1, Page 716; Found stone and plow point, Raised with Iron and Cap. Corner is $\pm 2'$ North of centerline East-West road and on old fence lines North and South N43E-8" Scotch Pine-64.00, N53W-Top Center Telephone Riser-54.80, S37E-8" Scotch Pine-76.10 Found Nail, S05W-Power Pole-80.08 Found Nail
- G-13) 1995 Wade-Trim Survey, Liber S-3, Page 256; Found Iron and Cap, S9W-Power Pole-80.8, S30E-10" Scotch Pine-75.9, N40W-Telephone Pedestal-54.93, North-Steel Post-34.7