

JAN 28 1999

Montmorency County Remonumentation

Liber 00012 Page 0335

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MONTMORENCY  
(County)

Located in:

Corner Code #

STATE OF MICHIGAN  
MONTMORENCY COUNTY  
Recorded & Filed

12-07-1998 09:38:21

MARY JO GUEST  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. ALBERT TWP.  
Public Land Survey  
T 29N R 1E E - 2
2. Property Controlling  
in Section  
S T R
3. Miscellaneous  
Property in Sec.  
S T R
4. Lot No. , Recorded Plat
5. Private Claims

I, DONALD E. MARLATT, in a field survey on MAY, 19 98, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E - 2 1/4 COR. COMMON TO SEC.'S 4 & 5.  
GLO CORNER SET LEWIS CLASON IN APR. 1840.  
SPR. PINE 10" S30W 30 L. - Y. PINE 12" S21E 58 L.  
CORNER WAS FOUND BY WILCOX & ASSO. INC. IN 1989. NO DESCRIPTION OR WITNESSES.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E - 2 1/4 CORNER COMMON TO SEC.'S 4 & 5.  
FOUND NO EVIDENCE OF CORNER. POSITION FALLS IN PIPE LINE AND IN LINE WITH OLD BRUSH LINE TO THE NORTH. RESET CORNER USING WILCOX ASSO. INC. DISTANCE NORTH-SOUTH & EAST. MATCHED WILCOX ASSO. INC. BEARING ON SECTION LINE.

APPROVED BY  
PEER GROUP

JUL 28 98

*LJB*



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E - 2 1/4 CORNER COMMON TO SEC.'S 4 & 5.  
SET CONC. MONUMENT AND REMON. CAP. (NORTH EDGE OF ROAD & SOUTH EDGE OF PIPE LINE).  
N 2°W 9" J. PINE 67.16'  
N33°W 8" J. PINE 83.87'  
N48°W 9" J. PINE 67.72'  
S15°E 6" J. PINE 77.59'

WITNESSES MARKED WITH 40 PENNY SPIKES AND P.S. TAGS#18660.  
APPROVED BY PEER GROUP ON JULY 28, 1998 AS A CAREFUL AND FAITHFUL ESTABLISHMENT OF THE POSITION OF THE CORNER.

Signed by *Donald E Marlatt*

Date 12/4/1998

Surveyor's Michigan License No. 18660