SURVEY & REMONUMENTATION

Montmorency County Remonumentation

FEB 0 6 1998

SECTION

For corners in

Liber 00012 Page 0245

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	Montmorency (County)	Located In: Albert Township	Corner Code =##	STATE OF MICHI MONTMORENCY CO Recorded & Fil	YTALIG
	Public Land Survey Property Controlling	T <u>29N</u> R <u>1E</u> T R T R T R S T R	L-5	10-17-1997 11: A. PANGAN-MCEL REGISTER OF DE	:40:19 .R0Y
	in Section Miscellaneous Property in Sec.	S T R S T R S T R			Stamp & File Number
4. 5.	Lot No, R	lecorded Plat			E F G H I J K L
do l in II cur Mai abo Cou	hereby certify that under req ines 1 and 2 above were in rent manual of survey instru nagement or by a decree of a ove were in conformance wit	in a field survey on June 12 urrements of P.A. 74, Michigan P.A. of the conformance with regulations and ructions of the United States Department Court of Law and/or that the corner point the rules of the Michigan Board of Law e-established, monumented, re-mon	970, the corner points menticules therefore as required in int of the Interior, Bureau of Libints mentioned in lines 3, 4 a and Surveyors or by a Decree	oned 6 18 17 17 17 18 18 19 19 19 19 19 19 19 19 19 19 19 19 19	9 10 11 1; 9 10 11 1; 16 15 14 13
•		orners, all in the same town and r	range, may be recorded	10 30 29	28 27 26 25 33 34 35 36
Α.	Description of original n L-5 ¼ corner for Sect	nonument and accessories and/or cions 12 & 13.	subsequent restoration:	13	
3.	Date unknown- Surveyor unknown, Set $\frac{1}{2}$ " x 3' rod from both Bts July 1971 & June 1972- Norman C. Caldwell P.S. #12018, Fnd. $\frac{1}{2}$ " x 3' rod in cluster of rocks. Placed $\frac{1}{2}$ " bar & RLS cap. Fnd. Bt's. Two Cert. of Sur. One Rec. L. 1, Pgs. 216-222. Wit's mkd: (S 18° W 15.8' 20" P. stp.) (BT) (N 78° W 15.1' remains of P. stp.) (S 40° W 48.6' 20" R. Pine) (S 70° W 7.3' 14" Oak) (N 80° E 22.6' 8" Maple) (N 80° E 5.1' Fe. Cor. post) L.C.R.C. Rec. L. 1, P.26. Same wit's as above. Feb. 1983- Donald E. Marlatt P.S. #18660, Fnd. $\frac{1}{2}$ " bar & cap by Caldwell. Cert. of Sur. Rec. L. 3, P. 294. Wit's r (S 80° W 15" Oak 7.3') (N 85° W 12" Maple 22.76') (N 45° W 10" Maple 6.35'). Description of corner evidence found and/or method applied in restoring or reestablishing corner: Fnd. $\frac{1}{2}$ " bar & RLS cap by Caldwell along side of $\frac{1}{4}$ " x 36" rod in cluster of rocks & Fnd. remains of B.T. S 18° W 14.8' (M) 15.8' (R) this cor. is 5.1' W of Fe. cor. Re-placed with conc. mon. & Re-mon cap. Red Top Post 2' $\frac{1}{2}$ SE.				
	L-5 # corner for Secti	t for corner and accessories estat ions 12 & 13.			
	Group on June 20, 1997 N 85° E 23.0' (R) 22.6	,	APPRO	OVED BY	OF MI
	N 45° E 19.12' 7" W. F N 43° W 6.28' 12" Map1 S 50° W 10.82' 8" Tw. N 20° E 17.75' 9" P. s	Pine (NBT) e (R) Maple.		GROUP.	LARRY G. BEAUREGAFD
		e, P.S. tag #18654 & blaze. (ty		CENT	SURVEYOR & NO. 18654
ane	ed by Lan	y S.Beauricaid	Date	10/17/97	ESSION

18654

Surveyor's Michigan License No.