

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 29 N.R. 1 E  
T. 29 N.R. 2 E


Montmorency COUNTY

DESCRIPTION OF CORNER Sec. corner common to sections 1-12-6-7

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED May 4, 1966

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

|                  |        |       |
|------------------|--------|-------|
| 10" Cedar        | S 60 E | 40.7' |
| 12" R. Pine      | N 70 E | 16.1' |
| 20" R. Pine stub | S 57 W | 29.7' |

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey of Section 6. Found 1 1/2" pipe at corner as established in previous survey from USBTs. Both stumps in place, the SW with some evidence of face. Checks very well with stream east.

SURVEYOR'S SEAL

SIGNED *Lincoln J. Ostling* DATE May 6, 1966  
REGISTERED LAND SURVEYOR #10068