STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		MONTHOREN	CY COUNTY
		T <u>29 N</u>	R 2 E
DESCRIPTION OF CORNER	E 1/16 cor. on S. Bo	oundary Sec. 33, T29N	R2E
CORNER MONUMENT	Set 1-3/4" pipe in (concrete block	
DATE MONUMENT PLACED AN	D WITNESSED	12-15-70	
WITNESSES TO CORNER	·· _ S" Haple in clump	N 48 W	39,11
N		N 28 E	37.81
33		East	12.851
CIRCLE CORNER REGISTE	AND		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by standard survey procedure to mark state land boundary.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGN

SIGNED LILITED LAND SURVEYOR 1908

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing