LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

I. Kenneth J. Ostling do hereby certify that under requirements of P.A. 74, Michigan P. the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) field survey on Musist 17,	LOCATE	CORNERS OF -:	'ED IN-:	CORNER	CODE NUMBER	
N. RECORDED PLAT 4. LOT NO	т. <u>29</u>	UBLIC LAND SURVEY	N., R. 3 €	C-7; E-	1; E-3	
N. RECORDED PLAT 4. LOT NO	,T	ROPERTY CONTROLL- ING IN SECTION——	N E			
I, Kenneth J. Ostling do hereby certify that under requirements of P.A. 74, Michigan P.J. the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) field survey onAugust 17,						
the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) field survey on August 17, 1973, established, re-established, monumented, re-monumented, resolved as expressed below and in conformance with regulations and rules therefore as required in the current of survey instructions of the United States Department of the Interferor, Bureau of Land Management of by a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field property instructions of the United States Department of the Interferor, Bureau of Land Management of by a court of law. Formance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of law. A. Description of original monument and accessories and/or subsequent restoration: B. Description of original monument and accessories and/or subsequent restoration: Replaced wood stake set in previous survey by this Department. Corner for Section 32 and 33, T. 30 N., R. 3 E., is 9.9 feet west. Restored corner previously established in Department survey, but removed by local residents. C. Description of monument for corner and accessories established to perpetuate locating the position of C-7	CORDED PLA	OT NO, RECO	.AT			
the corner points mentioned in lines 1 and 2 above (identified with circles on index code disgram—over) field survey on August 17, 1973, established, re-established, re-established, re-established, re-established, re-established, re-monumented, retestored as expressed below and in conformance with regulations and rules therefore as required in the curr of survey instructions of the United States Department of the Interloit, Bureau of Land Management or by a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field 19—, found, recovered, restored, established or re-established as expressed below a formance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of law: A. Description of original monument and accessories and/or subsequent restoration: B. Description of original monument and accessories and/or subsequent restoration: C. Tound well point and ½ rebar, from previous surveys. Replaced wood stake set in previous survey by this Department. Corner for Section 32 and 33, T. 30 N., R. 3 E., is 9.9 feet west. Restored corner previously established in Department survey, but removed by local residents. C. Description of monument for corner and accessories established to perpetuate locating the position of C-7 Set DNR Mon. Set DNR Mon. Set DNR Mon. Set DNR Mon. below surface 12" R. Oak N82E 20.9' 7" Basswood S22W 6.3' 14" well point 12" well poi		RIVATE CLAIMS		···	· 	REGISTER OF DEEDS STAMP AND FILING NUMBER
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found well point and 1 rebar, from previous surveys. Replaced wood stake set in previous survey by this Department. Corner for Section 32 and 33, T. 30 N., R. 3 E., is 9.9 feet west. Restored corner previously established in Department survey, but removed by local residents. C. Description of monument for corner and accessories established to perpetuate locating the position of C-7 E-1 Set DNR Mon. Set DNR Mon below surface 12" R. Oak N82E 20.9' 7" Basswood S22W 6.3' 12" well point 11" Well point 6" Maple N65W 24.6' 6" Maple N65W 24.6' 6" Maple N16E 27.8' 11" Dead Elm N79E 50.5'	and in confo United State te, that the	corner points mentioned in the description of the law for the law	and 2 above (id 19 <u>73</u> , establish formance with re- ites Department of e corner points	lentified with ned, re-establi gulations and of the Interior, mentioned in lestablished wentioned in mestablished	shed, monument rules therefore Bureau of Land lines 3, 4 and 5 or re-established	ted, re-monumented, recovered or as required in the current manual Management or by a decree of a babove were, in a field survey on d as expressed below and in con-
Replaced wood stake set in previous survey by this Department. Corner for Section 32 and 33, T. 30 N., R. 3 E., is 9.9 feet west. Restored corner previously established in Department survey, but removed by local residents. C. Description of monument for corner and accessories established to perpetuate locating the position of C-7 E-1 E-3 Set DNR Mon. Set DNR Mon. Set DNR Mon. Set DNR Mon. below surface 12" R. Oak N82E 20.9' 7" Basswood S22W 6.3' 14" well point 11" W. Oak N08E 17.0' 8" Basswood S50E 11.6' 4" Maple N65W 24.6' 6" Maple N16E 27.8' 11" Dead Elm N79E 50.5' SIGNED BY LOCALLY OSTULING SURVEYOR'S MICHIGAN REGISTRATION NO. 10068 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY DATE CHIEF OF SURVEY PARTY DATE	onument and	Description of original mor	d accessories ar	d/or subsequ	ent restoration:	
Replaced wood stake set in previous survey by this Department. Corner for Section 32 and 33, T. 30 N., R. 3 E., is 9.9 feet west. Restored corner previously established in Department survey, but removed by local residents. C. Description of monument for corner and accessories established to perpetuate locating the position of C-7 E-1 E-3 Set DNR Mon. Set DNR Mon. Set DNR Mon. Set DNR Mon. below surface 12" R. Oak N82E 20.9' 7" Basswood S22W 6.3' 14" well point 11" W. Oak N08E 17.0' 8" Basswood S50E 11.6' 4" Maple N65W 24.6' 6" Maple N16E 27.8' 11" Dead Elm N79E 50.5' SIGNED BY LOCALLY OSTULING SURVEYOR'S MICHIGAN REGISTRATION NO. 10068 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY DATE CHIEF OF SURVEY PARTY DATE						
Replaced wood stake set in previous survey by this Department. Corner for Section 32 and 33, T. 30 N., R. 3 E., is 9.9 feet west. Restored corner previously established in Department survey, but removed by local residents. C. Description of monument for corner and accessories established to perpetuate locating the position of C-7 E-1 E-3 Set DNR Mon. Set DNR Mon. Set DNR Mon. Set DNR Mon. below surface 12" R. Oak N82E 20.9' 7" Basswood S22W 6.3' 14" well point 11" W. Oak N08E 17.0' 8" Basswood S50E 11.6' 4" Maple N65W 24.6' 6" Maple N16E 27.8' 11" Dead Elm N79E 50.5' SIGNED BY LOCALLY OSTULING SURVEYOR'S MICHIGAN REGISTRATION NO. 10068 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY DATE CHIEF OF SURVEY PARTY DATE						
7 Found well point and 1/2 rebar, from previous surveys. 1 Replaced wood stake set in previous survey by this Department. Corner for Section 32 and 33, T. 30 N., R. 3 E., is 9.9 feet west. 3 Restored corner previously established in Department survey, but removed by local residents. 4. C. Description of monument for corner and accessories established to perpetuate locating the position of C-7 E-1 E-3 Set DNR Mon. Set DNR Mon. Set DNR Mon. below surface 12" R. Oak N82E 20.9' 7" Basswood S22W 6.3' 14" well point 11" W. Oak N08E 17.0' 8" Basswood S50E 11.6' 4" Maple N65W 24.6' 6" Maple N16E 27.8' 11" Dead Elm N79E 50.5' SIGNED BY LOLLEL D OSTULING SURVEYOR'S MICHIGAN REGISTRATION NO. 10068 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY DATE DATE						
Replaced wood stake set in previous survey by this Department. Corner for Section 32 and 33, T. 30 N., R. 3 E., is 9.9 feet west. Restored corner previously established in Department survey, but removed by local residents. C. Description of monument for corner and accessories established to perpetuate locating the position of C-7 E-1 E-3 Set DNR Mon. Set DNR Mon. Set DNR Mon. Set DNR Mon. below surface 12" R. Oak N82E 20.9' 7" Basswood S22W 6.3' 14" well point 11" W. Oak N08E 17.0' 8" Basswood S50E 11.6' 4" Maple N65W 24.6' 6" Maple N16E 27.8' 11" Dead Elm N79E 50.5' SIGNED BY LOCALLY OSTULING SURVEYOR'S MICHIGAN REGISTRATION NO. 10068 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY DATE CHIEF OF SURVEY PARTY DATE						
Replaced wood stake set in previous survey by this Department. Corner for Section 32 and 33, T. 30 N., R. 3 E., is 9.9 feet west. Restored corner previously established in Department survey, but removed by local residents. C. Description of monument for corner and accessories established to perpetuate locating the position of C-7 E-1 E-3 Set DNR Mon. Set DNR Mon. Set DNR Mon. below surface 12" R. Oak N82E 20.9' 7" Basswood S22W 6.3' 14" well point 11" W. Oak N08E 17.0' 8" Basswood S50E 11.6' 4" Maple N65W 24.6' 6" Maple N16E 27.8' 11" Dead Elm N79E 50.5' 11" Dead Elm N79E 50.5' SIGNED BY CALLED OSTAINS MICHIGAN REGISTRATION NO. 10068 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF BURNEY PARTY DATE	dence found	Description of corner evidence	d and/or method	applied in res	toring or re-esta	ablishing corner:
Restored corner previously established in Department survey, but removed by local residents. C. Description of monument for corner and accessories established to perpetuate locating the position of C-7 Set DNR Mon. Set DNR	nd ½ reba	Found well point an	ar, from pre	vious surve	eys.	
by local residents. C. Description of monument for corner and accessories established to perpetuate locating the position of C-7 E-1 E-3 Set DNR Mon. Set DNR Mon. Set DNR Mon. below surface 12" R. Oak N82E 20.9' 7" Basswood S22W 6.3' 14" well point 11" W. Oak N08E 17.0' 8" Basswood S50E 11.6' 4" Maple N65W 24.6' 6" Maple N16E 27.8' 11" Dead Elm N79E 50.5' SURVEYOR'S MICHIGAN REGISTRATION NO. 10068 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY DATE	e set in j T. 30 N.	Replaced wood stake Section 32 and 33,	previous su., R. 3 E.,	rvey by thi is 9.9 feet	is Departmen : west.	t. Corner for
Set DNR Mon. Se	eviously	Restored corner pre by local residents.	established	in Departm	nent survey,	but removed
Set DNR Mon. Set DNR Mon. Set DNR Mon. Set DNR Mon. below surface 12" R. Oak N82E 20.9' 7" Basswood S22W 6.3' 11" W. Oak N08E 17.0' 8" Basswood S50E 11.6' 4" Maple N65W 24.6' 6" Maple N16E 27.8' 11" Dead Elm N79E 50.5' KENNETH SURVEYOR'S MICHIGAN REGISTRATION NO. SURVEYOR'S MICHIGAN REGISTRATION NO. SIGNED BY CHIEF OF SURVEY PARTY DATE DATE DATE	t for corner	Description of monument	r and accessorie	s established	to perpetuate lo	cating the position of the corner:
SIGNED BY Lewell J Ostling DATE SURVEYOR'S MICHIGAN REGISTRATION NO. 10068 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY KENNETH J. OSTLING SURVEYOR NO. 10068 LAND SURVEYOR DATE CHIEF OF SURVEY PARTY	7" Ba	R Mon. Oak N82E 20.9'	DNR Mon. asswood S22	W 6.3' E 11.6'	1¼" well 4" Maple 6" Maple	n. below surface point N65W 24.6' N16E 27.8'
SIGNED BY DATE	2/				DATE	KENNETH J. OSTLING J. AHID7 3 SURVEYOR No. 10058
CHIEF OF SURVEY PARTY	STATES AG	OR STATE AND UNITED S	GENCIES:			CAND SOME
	CHIEF OF	GNED BY	OF SURVEY PARTY		DATE	
*** * *** * **** TTTT TTTTT TTTTT T LAICHIG AN REGISTERED LANU BUNYETUR				O LAUN AUNUMENA	DATE	
(SEAL)	~					(SEAL)

C-7

E-1

E-3

SURVEYOR'S MICHIGAN REGISTRATION NO.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN BOCIETY OF REGISTERED LAND SUPPLYORS