LAND CORNER RECORDATION CERTIFICATE

	Filing Requirement of Act 74, Mi	ch. PA 1970
For Corners In: Montmorency	Located In Corner Code #	
(County)	Codica III Collel Code #	
1. Public Land Survey	T R	EC .
Property Controlling in Section	S 15 T 29N R 3E 13	
2 Missellonenus	S	
Miscellaneous Property in Section	S T R	
	s T R	Register of Deeds Stamp & File Number
4. Lot No:		register of beaus Stallip & File Number
	Recorded Plat:	ABCDEFGHIJKLM
5. Private Claims:		2 6 5 4 3 2
A. Description of original 13- This corner positio	survey on October 15, 2007 do hereby state that under chigan PA of 1970, the corner points mentioned in lines 1 mance with regulations and rules therefore as required in vey instructions of the United States Department of the nagement or by a decree of a Court of Law and/or that the lines 3, 4 and 5 above were in conformance with the rules Land Surveyors or by a Decree of a Court of Law; monumented, recovered, found as expressed below: 2 corners, all in the same town and range, may rtificate. monument and accessories and/or subsequent restorating was not established during the arrow.	3 4 7 8 9 10 11 12 31 32 33 34 35 36 36 36 36 36 36 36 36 36 36 36 36 36
13-Established the No.	evidence found and/or method applies in restoring or re- rthwest corner of the Southeast st quarter of section 15 as per B.L.M. edivision of a section.	establishing corner:
C. Description of monum	ent for corner and accessories established to perpetuate	e locating the position of the corner:
13-Set 5/8" X 32" iron i Wit: Nail & Tag 8" N Nail & Tag 6" N Nail & Tag 6" N Nail & Tag 6" N Carsonite Post	rod with P.S. cap #33981 flaple N32°W 7.00' flaple S80°E 8.69' flaple N42°E 31.02' flaple S32°W 7.97'	CARL KIISKILA LAND SURVEYOR No. 33981 LAND SURVEYOR

Signed by:

Surveyor's Michigan License No.:

33981