

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED
MONTMORENCY CITY
REGISTRY OF DEEDS
DEC 20 10 12 AM '93
A. PANGAN-MCELROY

For corners in Montmorency (County) Located in: Corner Code ##

1. Public Land Survey T 29N R 3E A-8
T 29N R 3E A-9 ✓
T _____ R _____
T _____ R _____

2. Property Controlling S _____ T _____
in Section S _____ T _____

3. Miscellaneous S _____ T _____
Property in Sec. S _____ T _____

APPROVED BY
PEER GROUP
NOV 0 5 93

Register of Deeds Stamp & File Number

Lot No. _____, Recorded Plat _____
Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Donald E. Marlatt, in a field survey on December 10, 19 93
hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

- (8) W. $\frac{1}{4}$ Cor. Sec. 19, T29N, R3E (A-9) S.W. Cor. Sec. 19, T29N, R3E
Post set by Lewis Clason 1839. Post set by Lewis Clason 1839.
W. Pine 10-S 59 W-16 Y. Pine 22-S 54 W-1.76
W. Pine 10-N 24 W-42 Beech 10-S 65 E-39 Hemlock 28-N 68 W-33
M.S.H.D. Project 60-10 field notes 1956 M.S.H.D. Proj. 60-10 field notes 1956
Act 74 by D.E. Porter L. 1, P. 492 Act 74 D.E. Porter L. 1, P. 8
Survey by D.E. Marlatt L. 2, P. 121 Survey by Fred King L. 3, P. 520
Survey by Fred King L. 3, P. 520 Survey by D.E. Marlatt Dated 10-13-1981
Survey by D.E. Porter for Shell Western Survey by D.E. Porter for Shell Western
E. & P. Feb. 1993. E. & P. 1993.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- (8) W. $\frac{1}{4}$ Cor. Sec. 19, T29N, R3E (A-9) S.W. Cor. Sec. 19, T29N, R3E
Fnd. $\frac{1}{2}$ " rod. Fnd. $\frac{1}{2}$ " rod by DE La Mater 1932.
S 10° E 5.60' 12" Oak 22" Oak N 54° W 35.32'
N 80° W 20.07' 8" Oak 8" Oak S 14° E 20.38'
N 15° E 14.89' 12" Oak 9" Oak N 83° E 20.0'
N 1° E 35.85' 16" Oak

No evidence of original corner.

No evidence of original corner.

The Peer Group approved (A-8) & (A-9) as the best available evidence of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- (8) W. $\frac{1}{4}$ Cor. Sec. 19, T29N, R3E (A-9) S.W. Cor. Sec. 19, T29N, R3E
Placed Re-Mon. cap on $\frac{1}{2}$ " rod. Placed Re-Mon. cap on $\frac{1}{2}$ " rod.
S 17° E 5.60' 12" Oak N 55° W 24" Oak 33.98'
N 70° W 19.93' 10" Oak S 50° W 14" Oak 35.52'
N 35° E 14.89' 12" Oak S 9° E 14" Oak 20.33'
N 8° E 35.88' 16" Oak N 87° E 12" Oak 30.00'

Witnesses marked with 30 penny spikes & I.D. tags #18660.

igned by Donald E. Marlatt

Date Dec 15, 1993

urveyor's Michigan License No. 18660

