

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Montmorency (County)	Located In	Corner Code #
1. Public Land Survey	T 29N R 3E	K-9
	T 29N R 3E	J-9
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Section	S T R	
	S T R	
4. Lot No:	Recorded Plat:	
5. Private Claims:		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		8		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Carl T. Kiiskila, in a field survey on March 31, 1999 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

K - 9 GLO - Lewis Clawson D.S. 1839

Set corner post Sections 23, 24, 25 and 26.

Wit: Yellow Pine 22" SE 1.13 chains
Yellow Pine 20" N33E 1.02 chains

J - 9 GLO - Lewis Clawson D.S. 1839

Set quarter section post.

Wit: Yellow Pine 24" N 18° W 36 links
Yellow Pine 26" S 53° E 57 links

K. Ostling PS #10028 July 1977 found and accepted a 2" pipe in a monument box.

K. Ostling PS #10028 July 1977 set standard D.N.R. monument by proportionate measurement.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

K-9 Found and accepted a 2" iron pipe in a monument box. J-9 Found and accepted a standard D.N.R. monument.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-9 Found 2" iron pipe in a monument box.

Wit: 9" Maple S 56° W 41.22'
12" Maple N 38° W 55.52'
10" Oak N 63° E 76.31'
4" Maple S 55° E 55.02'

Centerline of north-south
blacktop (M-33) East 2.5'

J-9 Found a standard D.N.R. monument.

Wit: • 7" Oak N 09° E 16.72'
• 7" Oak S 68° E 9.48'
10" Oak S 10° E 15.57'
8" Oak S 63° W 22.30'

• Old witness by others

Signed by:

Carl T Kiiskila

Date:

5-26-99

Surveyor's Michigan License No.:

33981