REMONUMENTATION

Montmorency County Remonumentation

APR 2 4 1995

Private Claims

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

$00012_{ m Page}009$) ,

ALCI COMPANAIMINA CONTRA		
Montmorency (County)	Located In: Loud T	wp. Corner Code ##
Public Land Survey	T <u>29N À 3E</u> T R	<u>(J-13)</u>
	T R T R	APPROVED BY

STATE OF MICHIGAN MONTMORENCY COUNTY Recorded & Filed

11-02-1994 15:41:38

A. PANGAN-MCELROY REGISTER OF DEEDS

Register of Deeds Stamp & File Number

	Montmorency (County)	Located In: Loud Twp. Corner Code ##
1.	Public Land Survey	T 29N R 3E (J-13)
2.	Property Controlling	T R APPROVED BY T R PEER GROUP
	in Section	S T AUG 0 5 94
3.	Miscellaneous Property in Sec.	S T R S

May Larry G. Beauregardin a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10

A. Description of original monument and accessories and/or subsequent restoration:

GLO post set by Lewis Clason December 12, 1839. Wits: Beech 12" N 55° E 20 links

Beech 9" N 19° W 52 links

Delmar E. Porter P.S. #15410 in 1971 re-set ½" bar & P.S. cap by S.P. method. Wits marked: (N 50° E 34.23' 8" Oak), (Due North 14.40' 12" Oak) and (S 60° W 71.67' 12" Maple).

Norman C. Caldwell P.S. #12018 in 1977 found ½" rod by Porter and replaced it with a standard County corner. Recorded L. 2, P. 438. Wits marked: (N 50° E 36.8' 8" Oak), (North 15.4' 12" Oak), (S 60° W 69.0' 12" Maple (West 6.6' standard County corner). (Oscoda County Recorde, Recorded L. 2, P. 438).

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- Didn't find corners set by Caldwell in 1977. I did find two red top posts and one record witness by Caldwell. (J-13)Also found two recorded witnesses by Parter, but they didn't agree with the Caldwell witnesses. So I re-ran the County line and set a 4" x 36" concrete monument with a 3" diam., Aluminum cap #18654 marked Montmorency County Remonumentation corner by S.P. method between (R) SE & Sul corners on the County line.



C. Description of monument for corner and accessories established to perpetuate locating the position of the c

(J-13) 1 corner common to Sec. 35, T 29 N, R 3 E

Concrete mon. & Re-mon. cap, P.S. #18654. Accepted as a careful and faithful establishment of the position of the corner. Approved by the Peer Group on August 5, 1994.

Tw. 8" Maples N 15° E 36.83' P. Pole S 05° E 51.85' -- Placed P.K. mail & P.S. tag #18654 in pole 6" Maple N 45° E 38.281 4" Ballsam S 35° W 103.50'

Placed blaze, 20 penny spike & P.S. tag #18654 (typ)

_ Date __

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197 REVISED MAY 14. 181

REVISED JAH., 191