## Montmorency County Remonumentation

LAND	CORNER	RECO	RDATIO	N CER	TIFIC	CATE
Filing	Requirem	ent of	Act 74,	Mich.	P.A.	1970

For conters in		•		
	MONTMORENCY	Located In:	Corner Code ##	
_	(County)	RUST TWB.		
1.	Public Land Survey	T 29N R 4E	(A-10)	
		T 29N R 4E	A-II	
		T R	·	
		T R		
2.	Property Controlling	S T R	<del></del>	
	in Section	S T R		
3.	Miscellaneous	S T R	· · · · · · · · · · · · · · · · · · ·	
	Property in Sec.	S T R		

Register of Deeds Stamp & File Number

08225

Lot No, Recorded Plat _ Private Claims			

\_ , in a field survey on \_ August - September , 19 93 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

West 1/4 Cor., Sec. 30, T.29 N., R.4 E. Orig. Post by Lewis Clason - Nov. 1839

S52W-31 lks(20.46')Tam, N28W-36 lks(23.76')Tam

1971-Un-Rec Sur by N. Caldwell - Set Conc. Mon.

Does not indicate Corner Evidence Fnd or Mthd Used

S15E-25.0'-3" Map, S75W-29.3'-3" Map, N30W-33.0'10" Oak

NO ACT 74 RECORDED FOR THIS CORNER

A-11 SWMCor. Sec. 30 & NW Cor. Sec. 31, T.29 N., R.4 E. Orig. Post by Lewis Clason - Nov. 1839 S66W-29 Iks(19.14')Hem, N65W-42 1ks(27.72')Maple 1971-Un-Rec Sur by N. Caldwell - Placed 1/2" Iron & Cap in Fnd 14" Pipe - Does not Indicate who:Set Pipe S12E-43.3'- 5" Maple, S.58W-31.6'- 10" Oak N20E-63.2'- 6" Birch, NORTH-33.0'-DNR Mkr Post NO ACT 74 RECORDED FOR THIS CORNER

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-10 West 1/4 Cor., Sec. 30, T.29 N., R.4 E. Fnd. Rec. Conc. Mon. (Caldwell Sur) S.15°E - 25.0'--3" Maple (Rec) S.75°W - 29.3'- 3" Maple (Rec) (Now Dead) N.300W - 33.0'-10" Oak (Rec) NO ORIGINAL CORNER EVIDENCE FOUND

A-11 SW Cor. Sec. 30 & NW Cor. Sec. 31, T.29 N., R.4 E. Fnd. Rec. Irons& Cap in 14" Pipe (Caldwell Sur) NORTH - 33.0' - DNR Mkr Post@(Rèc) N.20°E. - 63.2' - 6" Birch (Rec) NO ORIGINAL CORNER EVIDENCE FOUND

Approved by Montmorency County Peer Review on Sept. 24. 19932 as a careful and faithful re-establishment of the position of the corner.

Approved by Montmorency County Peer Review on Sept. 24, 1993, as the best available evidence of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-11 SN Cor., Sec. 30 & NW Cor Sec. 31, T.29 N., R.4 E.

A-10 West 1/4 Cor., Sec. 30, T.29 N., R.4 E. Set Mont.CCo. Re-Mon Cap on Fnd. Conc. Mon. S.75°E. - 7.00 - Set Tag SW Sd. 8" Maple S.15°E. - 25.12'- Set Tag E. Sd. 6" Maple N.600W. - 11.30'--SettTaggSW Sd. 6" Twin Maple N.300W. - 33.34'- Set Tag E. Sd. 18" Oak Fnd. Cedar R.T. Post Along Side Corner

Set Mont. Co. Re-Mon Cap on Fnd 1/2" Iron in Pipe Corner is in C.L. E-W Dirt Rd. (McIntire Rd) Corner is ±3' W of Fnc to S.

NORTH - Set Tag E. Sd. Cedar R.T. Post

N.20°E. - 63.47' - Set Tag E. Sd. 12" Birch

S.60°E. - 33.24' - Set Tag SW Sd. 8" Maple Birch S.10°E. - 16.28' - N Face of Steel Fnc Cor Post N.55°W. - 28.62' - Set Tag SW Sd. 8" Poplar 5.10°E.

NOTE: All Witnesses Marked with Dbl. Headed Nails & I.D. Tag #25852, unless otherwise noted

na na anakana na mangangkan katangkan katangkan katangkan katangkan katangkan katangkan katangkan katangkan me

Frederick Signed by Surveyor's Michigan License No.

\_\_ Date \_\_Dec.\_ 23,

FREDERICK J. KING **PROFESSIONAL** SURVEYOR No.

25852 POFESSIO