

Montmorency County Remonumentation

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MONTMORENCY
(County)

Located In:

Corner Code ##

VIENNA TWP.

- | | | |
|------------------------------------|--------------------------|-------------|
| 1. Public Land Survey | T <u>30N</u> R <u>1E</u> | <u>A-13</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Frederick J. King, in a field survey on August - September, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- A-13 Southwest Corner of Sec. 31, T.30 N., R.1 E.
Orig. Post by Lewis Clawson, D.S. - April 1839
S.33°E. - 28 lks (18.48') W. Pine
N.49°E. - 72 lks (47.52') J. Pine
NO REC. ACT 132 FOUND FOR THIS CORNER
NO REC. ACT 74 FOUND FOR THIS CORNER

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- A-13 Southwest Corner of Sec. 31, T.30 N., R.1 E.
Fnd. 1/2" Iron & Wakenhut I.D. Cap
N.05°E - 42.11' - Fnd. Wakenhut Tag - 10" Oak
S.55°E - 32.69' - Fnd. Wakenhut Tag - 12" Oak
NO ORIGINAL CORNER EVIDENCE FOUND

This Cor. is the STANDARD CORNER on the MICHIGAN MERIDIAN.

Approved by Montmorency County Peer Review on Sept. 24, 1993, as a careful and faithful perpetuation of the Original Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- A-13 Southwest Corner of Sec. 31, T.30 N., R.1 E.
Set Mont. Co. Re-Mon Cap on Fnd. 1/2" Iron
Corner is 37' E of N-S Pwr Line
N.10°E. - 10.37' - Set Tag W. Sd. 10" Oak
N.55°E. - 44.90' - Set Tag NW Sd. 6" Maple (Old W&T)
S.40°E. - 22.14' - Set Tag SW Sd. 8" Maple
S.35°W. - 11.92' - Set Tag SE Sd. 6" Oak (Old Wit)
Set Treated R.T. Post Along Side Corner

NOTE: All witnesses Marked with Db1. Headed Nails & I.D. Tag #25852

Signed by Frederick J. King Date Dec. 23, 1993

Surveyor's Michigan License No. 25852

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

08222

RECEIVED
MONTMORENCY CITY
REGISTERED DEEDS
DEC 23 3 00 PM '93
A. PANICAN-MCELROY

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

