

Montmorency County Remonumentation

Liber 12 Page 56

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Montmorency (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>30N</u> R <u>2E</u>	(A-6)
	T <u> </u> R <u> </u>	
	T <u> </u> R <u> </u>	
	T <u> </u> R <u> </u>	
2. Property Controlling in Section	S <u> </u> T <u> </u> R <u> </u>	
	S <u> </u> T <u> </u> R <u> </u>	
3. Miscellaneous Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	
	S <u> </u> T <u> </u> R <u> </u>	

RECEIVED
 MONTMORENCY COUNTY
 REGISTERED
 DEC 28 9 06 AM '93
 A. PAISON-MCELROY

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Larry G. Beauregard in a field survey on October, 19 93,
 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
 current manual of survey instructions of the United States Department of the Interior, Bureau of Land
 Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
 Court of Law; established, re-established, monumented, re-monumented, recovered, found as
 expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
 on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

(A-6) GLO Post set by Lewis Clason April 1840 wits (none).
 Marked Hard Maple 12" for corner.
 Donald E. Marlatt P.S. #18660 in 1978 set R.R. spike by S.P. method, Survey Rec. L. 2,
 P. 511. Wits marked: (N 88° W 42.85' 5" Maple) (N 80° E 48.45' 12" Maple)
 (S 65° E 63.0' 12" Maple).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A-6) Fnd. R.R. spike set by Marlatt & wits above.
 Re-placed R.R. spike with 1/2" x 18" bar with 3" dia. Aluminum cap marked Montmorency
 Co. Re-Mon. Cor. in Mon. box 5'± West of M-32 C/L.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A-6) 1/4 Cor. Comm. to Sec's 13 & 18, T30N, R1E & T30N, R2E
 1/2" bar & Re-Mon. cap #18654 in Mon. box, accepted as a careful and faithful establishment
 of the position of the corner, approved by the Peer Group on September 24, 1993.
 N 88° W 42.85' 7" Maple (R) NBT S 65° E 63.0' 14" Maple (R) NBT
 N 80° E 48.45' 14" Maple (R) NBT N 89°-11'-27" W 133' Ex. bar & cap
 #18660
 N 88°-37'-29" E 133' Ex. bar & cap
 #18660
 (Placed blaze, 20 penny spike & P.S. tag #18654) (typ)

Signed by Larry G. Beauregard Date 12-27-93
 Surveyor's Michigan License No. 18654