



MONTMORENCY COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Montmorency</u> (County)	Located in: <u>Briley</u> (Township)	Corner Code #
1. Public Land Survey	T <u>30N</u> R <u>2E</u>	<u>K-9</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling In Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

08-10-1999 14:41:53

TERESA WALKER
REGISTER OF DEEDSRegister of Deeds Stamp & File
Number

I, Larry G. Beauregard, in a field survey on April, 1999 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
K-9 - Sec. Corner common with 23, 24, 25 & 26 T30N, R2E

1840 - Lewis Clason, D.S. Set Post. Wit's mkd. (Tam. 6" S19E 24 lks)
(No other tree convenient).

1972-1973 - Delmer E. Porter, RLS #15410. Fnd. 3" x 3" sq. Cedar Stk. 3' S. of waters edge & Two NBT's. Filed LCRC, Rec. L. 1, Pg. 4 & in 1973. Filed Act #132, Rec. L. 1, Pgs. 292 - 298. Wit's Fnd. (S75°W 10.40' 6" Tam.) (Mkd. NBT) (Due E. 7.60' 6" Tam.) (Mkd. NBT) (S45°E 16.70' 9" Tam.) NBT.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

April, 1999 - Fnd. 1/2" bar & cap #15410 by Porter in the top of a 3" x 3" Cedar Stake 3' South of waters edge & Wit's by Porter & others.
Replaced Stk. with a 3 1/4" Aluminum Re-mon. cap on a 4" dia. X 36" concrete monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
K-9 - Sec. Cor. common with 23, 24, 25 & 26 T30N, R2E

3 1/4" Aluminum Re-mon. cap on 4" dia. X 36" concrete monument.

Accepted as the best available evidence of the original corner.

Approved by the Peer Group on July 20, 1999.

S56°E	16.20'	8" Tamarack	(R) (Placed 60d Spike & P.S. Tag 18654)
S75°E	10.40' (R & M)	6" "	(R) (" " " " " ")
East	7.60'	6" "	(R) Stump with blaze
S42°W	8.60'	5" Cedar	(Placed 60d Spike & P.S. Tag 18654)
S30°W	21.40'	9" "	(" " " " " ")

APPROVED BY
PEER GROUP

JUL 20 99

L.G.B.

Signed by Larry G. Beauregard
Surveyor's Michigan License No. 18654

Date, August 5, 1999

SURVEY &
REMONUMENTATION

NOV 23 1999

SECTION