

SURVEY & REMONUMENTATION

JAN 22 2001

Montmorency County Remonumentation

Liber 00012 Page 0435

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
MONTMORENCY

(County)

Located In:
BRILEY TWP.

Corner Code #

1. Public Land Survey

T 30N R 2 E C-1
T R
T R
T R
T R

2. Property Controlling
in Section

S T R
S T R
S T R
S T R

3. Miscellaneous
Property in Sec.

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

12-05-2000 10:04:45

TERESA WALKER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

DONALD E MARLATT in a field survey on MAY 19XX 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

C-1 NORTH COR. COMMON TO SECTIONS 5 & 6

G.L.O. COR. SET BY LEWIS CLASON IN APRIL 1840. BEECH 10" S40°E 31 L, BEECH 10" S50°W 43 L. INTERSECTED THE THIRD CORRECTION LINE 74.05 CH. EAST OF TOWNSHIP CORNER.

G.G. SLATTERY P.E. M.S.H.D. SURVEY CHIEF SET 1 1/4" PIPE ON LINE BY GLO PROPORTION FEB. 1968. S85°E 60.53' 35" MAPLE, S15°W 32.37' 17" MAPLE, S35°W 58.86' 8" BEECH.

D.E. MARLATT P.S. #18660 FILED ACT 132 DATED 4/30/80 IN L. 3, P. 26. FOUND 1 1/4" PIPE BENT OVER, REPLACED WITH 1/2" ROD. WITNESSES THE SAME AS ABOVE.

D.E. MARLATT P.S. FILED ACT 132 DATED 4/30/80 IN L. 3, P. 27. WIT. & COR. DESCRIPTION SAME AS AB

D.E. MARLATT P.S. FILED ACT 132 DATED 4/30/80 IN L. 3, P. 28. WIT. & COR. DESCRIPTION SAME AS AB

L.G. BEAUREGARD P.S. # 18654 FILED ACT 74 DATED 6/3/89 & RECORDED IN L. 1, P. 430. FOUND 1/2" BAR & CAP #18660. WITNESSES SAME AS ABOVE.

D.E. MARLATT P.S. FILED ACT 132 DATED 8/16/97 AND RECORDED IN L. 10004, P. 512. FOUND 1/2" ROD.

NORTH 8"N. PINE 34.45', N70°E N. PINE 48.23', S 5°E 14" MAPLE 63.68', S35°W 10" BEECH 59.05'.

JAMES L SCHWANDT P.S. #26466 FILED ACT 132 DATED 8/17/99 AND RECORDED IN L. 10005, P. 125. FOUND 1/2" ROD. 36' MAPLE S85°E 60.53', 17" MAPLE S15°W 32.37', 8" MAPLE S35°W 58.86'.

B. Description of cor. evidence found and/or method applied in restoring or reestablishing cor.

C-1 NORTH CORNER COMMON TO SECTIONS 5 & 6.

FOUND 1/2" ROD & CAP 3' NORTH OF NORTH EDGE OF ROAD.

N 2°E 12" SCOTCH PINE 34.47' R. S 2°E 15" MAPLE 63.65' R.

N72°E 13" SCOTCH PINE 48.23' R. S39°W 15" BEECH 59.03 R.

C. Description of monument for corner and accessories established to perpetuate location of the corner:

C-1 NORTH CORNER COMMON TO SECTIONS 5 & 6.

SET CONC. MONUMENT AND REMON CAP

N 2°E 12" SCOTCH PINE 34.47'

N72°E 13" SCOTCH PINE 48.23'

S39°W 15" 15" BEECH 59.03'

S 2°E 15" MAPLE 63.65'

WITNESSES MARKED WITH 40 PENNY SPIKES AND P.S. TAGS #18660.

APPROVED BY PEER GROUP ON JULY 18, 2000 AS THE BEST AVAILABLE EVIDENCE OF THE REESTABLISHMENT OF THE ORIGINAL CORNER.

Signed by Donald E Marlatt

Surveyor's Michigan License No. 18660

Date 12/4/2000

APPROVED BY
PEER GROUP

JUL 18 00

L.G.B.

