

# SURVEY & REMONUMENTATION

JAN 22 2001

Montmorency County Remonumentation Liber 00012 Page 0437

## SECTION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MONTMORENCY

(County)

Located In:

BRILEY TWP.

Corner Code #/

C-3

1. Public Land Survey

T 30N R 2E

T R

T R

T R

2. Property Controlling in Section

S T R

S T R

3. Miscellaneous Property in Sec.

S T R

S T R

STATE OF MICHIGAN  
MONTMORENCY COUNTY  
Recorded & Filed

12-05-2000 10:05:16

TERESA WALKER  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

I, DONALD E MARLATT, in a field survey on MAY, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

C - 3 SECTION COR. COMMON TO SECTIONS 5-6-7 & 8.

GLO COR. SET BY LEWIS CLASON IN APRIL 1840. BEECH 20" N48°E 30 L., BEECH 22" S53°W 65 L.

G.G. SLATTERY P.E. MSHD SURVEY CREW CHIEF, SET 1 1/4" PIPE BY GLO PROPORTION IN FEB. 1968.

10' WEST OF N & S BARB WIRE, S65°E 13.8' 8" MAPLE, N30°W 37.7' 7" MAPLE, S32°W 10.2' 10" TW. MAPLE

D.E. MARLATT P.S. #18660 FILED ACT 132 DATED 6/3/73 & REC. IN L. 1, P. 380. FD. 2" PIPE (NO WIT.)

L.G. BEAUREGARD P.S. #18654 FILED ACT 132 DATED 12/19/97 & REC. IN L. 10004, P. 545. FOUND

1 1/4" PIPE, S65°E 13.8' 8" MAPLE, N30°W 37.7' 7" MAPLE R., S32°W 10.2' 10" TW. MAPLE R.

8" MAPLE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-3 SECTION COR. COMMON TO SECTIONS 5-6-7 & 8.

FOUND 1 1/4" PIPE

S58°E 12" MAPLE 13.54' R.

S15°E 9" BEECH 32.45'


S30°W TW. 9" MAPLE 10.5' R.

N85°W 19" POPLAR 24.85'

APPROVED BY  
PEER GROUP

JUL 18 00

*L.D.B.*



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-3 SECTION COR. COMMON TO SECTIONS 5-6-7 & 8

SET CONC. MONUMENT AND REMON. CAP.

S58°E 12" MAPLE 13.54'

S15°E 9" BEECH 32.45'

S30°W TW. 9" MAPLE 10.5'

N85°W 19" POPLAR 24.85'

WITNESSES MARKED WITH 40 PENNY SPIKES PS TAGS #18660.

APPROVED BY PEER GROUP ON JULY 18, 2000 AS THE BEST AVAILABLE EVIDENCE OF THE RE-ESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER.

Signed by

*Donald E Marlatt*

Date

*12/4/2000*

Surveyor's Michigan License No.

18660