

SURVEY & REMONUMENTATION

JAN 22 2001

Liter 00012 Page 0403

SECTION

MONTMORENCY COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Located in:

Montmorency
(County)

Briley
(Township)

Corner Code #

1. Public Land Survey

T 30N R 2E

C - 11

2. Property Controlling
in Section

S

T R

3. Miscellaneous
Property in Sec.

S

T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

10-27-2000 11:54:39

TERESA WALKER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Larry G. Beauregard, in a field survey on MARCH, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules thereof as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C - 11 Section corner common to Sections 29 - 30 - 31 & 32:

1840 Lewis Clason D.S. Set Cor. Sec. 29 - 30 - 31 & 32. Wit's. Mkd. (W. Pine 26" N33°W 40 lks.) (Beech 8" S19°W 27 lks.)

Date & Surveyor unknown. Set ¼" rod. No Wit's. Mkd.

1960 Leo R. Smith RLS #10706 (Surveyor for Scott Eng.) Fnd. & accepted its position in a section divisional survey of Sec. 30. No Wit's. Mkd.

1973 Delmer E. Porter P.S. #15410. Fnd. ½" rod & accepted its position in a section divisional survey of Sec. 32. Wit's. Mkd. (S03°W 62.68' 16" Oak) (N68°W 129.42' 22" W. Pine) (S25°E 55.18' 14" N. Pine) Filed Act #132 Rec. L. 1, P. 280. Same Wit's. Filed LCRC Rec. L. 1, P. 50. Same Wit's.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

March 2000: Fnd. ¼" rod, 29' ± SE Co. Rd. C/L. Re-placed pipe with 4" x 36" concrete monument with a 3/4" aluminum Re-mon. cap on top.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C - 11 Section corner common to Sections 29 - 30 - 31 & 32.
4" x 36" concrete monument with a 3/4" aluminum Mont. Co. Re-mon. cap.

Accepted as the best available evidence of the original government corner.

Accepted by the peer group on July 18, 2000.


N 68° W 129.42' 30" W. Pine (R)
S 25° E 55.18' 18" N. Pine (R)
S 03° W 62.68' 26" Twn. Oak (R)
S 86° E 62.75' 16" Oak (NBT)

Placed 60d penny spike & P.S. tag #18654 (typ).

APPROVED BY
PEER GROUP

JUL 18 00

L.G.B.



Signed by Larry G. Beauregard

Date 10-27-00

Surveyor's Michigan License No. 18654

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 26, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1985