

JAN 22 2001

Montmorency County Remonumentation

SECTION

**LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

Liber **00012** Page **0439**

For corners in

MONTMORENCY
(County)

Located in:

Corner Code #

BRILEY TWP.

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

12-05-2000 10:05:42

TERESA WALKER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land Survey

T30NR 2E D-1
T R
T R
T R
T R
S T R
S T R
S T R
S T R

2. Property Controlling
in Section

3. Miscellaneous
Property in Sec.

4. Lot No. , Recorded Plat

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

I, DONALD E MARLATT, in a field survey on MAV, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

D-1 N 1/4 COR. OF SEC. 5

NO G.L.O. COR. SET IN ORIGINAL SURVEY

G.G. SLATTERY P.E. MSHD SURVEY CREW CHIEF SET 1 1/4" PIPE IN FEB. 1968. SET ON LINE BY GLO PROPORTION 12' NORTH OF E&W FT. TRAIL & 50' EAST OF N & S DIRT TR. N20°W 22.75' 12" TW. ELM, N85°E 40.39' 13" TW. MAPLE, S60°E 16.96' 5" MAPLE, S45°W 39.09' 17" MAPLE.

COUNTY ROAD COMMISSION NOTES (NO DATE) SAME CORNER DESCRIPTION & WIT. AS ABOVE.

D.E. MARLATT P.S. #18660 FILED ACT 132 DATED 2/28/74 IN L. 1, P. 555. FOUND 1 1/4" PIPE. NO WIT.

L.G. BEAUREGARD P.S. #18654 FILED ACT 74, DATED 7/3/89 & RECORDED IN L.I. P. 430. FD. 1 1/4" PIPE N30°E 17.06' 4" MAPLE NBT, S60°E 19.96' 8" MAPLE R., N75°W 26.3' 4" MAPLE NBT.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-1 NORTH 1/4 CORNER OF SECTION 5.

FOUND 1 1/4" PIPE

S88°E TW. 8" MAPLE 40.32'

S50°E 9" MAPLE 16.95' R.

N40°E 9" OAK 26.35'

N60°W 8" MAPLE 26.39' NBT

N20°W 12" TW. ELM 22.75' STUMP R.

S45°W 17" ELM 39.09' STUMP R.

APPROVED BY
PEER GROUP

JUL 18 00

L.G.B.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-1 N. 1/4 COR. OF SEC. 5

SET CONC. MONUMENT AND REMON. CAP

N40°E 9" OAK 26.35'

S88°E TW. 8" MAPLE 40.32'

S50°E 9" MAPLE 16.95'

N60°W 8" MAPLE 26.39'

WITNESSES MARKED WITH 40 PENNY SPIKES AND PS TAGS # 18660

APPROVED BY PEER GROUP ON JULY 18, 2000 AS A CAREFUL AND FAITHFUL ESTABLISHMENT OF THE POSITION OF THE CORNER.

Signed by Donald E Marlatt

Surveyor's Michigan License No. 18660

Date 12/4/2000

