

SURVEY & REMONUMENTATION

JAN 22 2001

Montmorency County Remonumentation

Liber 00012 Page 0441

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MONTMORENCY
(County)

Located in:
BRILEY TWP

Corner Code #

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

12-05-2000 10:06:11

TERESA WALKER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land Survey

T 30N R 2E E-1

T R

T R

T R

2. Property Controlling in Section

S T R

S T R

3. Miscellaneous Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2	6	5			4		3		2		1	
3												
4	7	8			9		10		11		12	
5												
6	18	17			16		15		14		13	
7												
8	19	20			21		22		23		24	
9												
10	30	29			28		27		26		25	
11												
12	31	32			33		34		35		36	
13												

I, DONALD E MARLATT, in a field survey on MAY 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-1 NORTH CORNER COMMON TO SECTIONS 4 & 5

G.L.O. COR. WAS SET BY LEWIS CLASON IN APRIL 1840. Hd MAPLE 9" S51°E 75 L., BEECH 18" S28°W 2' G.G. SLATTERY P.E. MSHD SURVEY CREW CHIEF FOUND A CONC. MONUMENT IN FEB. 1968, 3" ABOVE GROUND AND 10' SOUTH OF E & W FENCE AND 10' NORTH OF E & W TRAIL C/L. N85°E 34.5' 38" MAPLE CLUMP, DUE NORTH 3.02' 4" MAPLE, N85°W 13.62' 6 MAPLE. COUNTY ROAD COMMISSION NOTES(NO DATE) CORNER DESCRIPTION AND WIT. THE SAME AS ABOVE.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-1 NORTH CORNER COMMON TO SECTIONS 4 & 5.

FOUND CONC. MONUMENT

S 7°W 9" MAPLE 27.3'

N85°W 13" MAPLE 13.56' R.

N 3°E 6" MAPLE 3.0' R.

N85°E 15" MAPLE IN CLUMP 32.35'

APPROVED BY
PEER GROUP

JUL 18 00

L.S.B.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-1 NORTH CORNER COMMON TO SECTIONS 4 & 5.

PLACED REMON. CAP ON EXISTING MONUMENT

S 7°W 9" MAPLE 27.3'

N85°W 13" MAPLE 13.56'

N 3°E 6" MAPLE 3.0'

N85°E 15" MAPLE IN CLUMP 32.35'

WITNESSES MARKED WITH 40 PENNY SPIKES AND P.S. TAGS #18660

APPROVED BY PEER GROUP ON JULY 18, 2000 AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

Signed by Donald E Marlatt

Date 12/4/2000

Surveyor's Michigan License No. 18660

