SURVEY & REMONUMENTATION

JAN 22 2001

Montmorency County Remonumentation

Liber 00012 Page 0424

	SE	EC.	TI	NC
For co	orners ir	1		

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MONIMORENCY	Located In: BRILEY	Corner Code #	STATE OF MICHIGAN	•
(County)			MONTMORENCY COUNT	ſY
1. Public Land Survey	T_30N R 2E	E-5	Recorded & Filed	
asiis aaiia sartoy	TR_		11-13-2000 13:33:	: 31
•	TR		2. 20 2000 10.00	W4
2. Dromorhi Combinillia	R		TERESA WALKER	•
2. Property Controlling in Section	S TR		REGISTER OF DEEDS	i
3. Miscellaneous	S TR S TR	<u> </u>		
Property in Sec.	S T R	<u></u>		
		•	Register of Deeds S	stamp & File Number
4 Lot No Boom	rdod Dlat			
4. Lot No, Recor 5. Private Claims			ABCDEF	GHIJKL
			- '	ĭïïïïïï
			2 6 5 1	1-3-1-1-
EREDERICK J. KING	. in a field survey on App	ii 7 ooo daharahaal		
requirements of r.A. 74. Michiga	ID MA OT 1970) The comer bold	nte mentioned in lines 4 sect n		10 11 12
United States Department of the I	rules therefore as required in thinterior. Bureau of Land Manage	he current manual of survey instr	ructions of the 5	
mar me comer boilts Metifoted	IN IIRES J. 4 BNO 5 Shove were i	in conformance with the rules of	Films hillington	15-14-13-
Board of Land Surveyors or by recovered, found as expressed bel	A Decree of a Court of Law	r; established, re-established,	monumented, 7	
NOTE: N			8 - 19 - 20 - 21 -	22 23 24-
NOTE: Not more than 2 com- on this certificate.	ers, all in the same town and	range, may be recorded	9	┠╸╏╶╏ ╌╏╌╏
on the continuate.			10 30 29 28	272625-
			11	
			12 -31 -32 - 33	-34-35-36-
A. Description of original mor	nument and accessories on	dor ou boom out roots with a	13	<u> </u>
E-5 - CORNER COMMON TO SEC	TIONS R Q 16 1 17	moi empsedneut testotation	:	
		1022 ⁰ H-6 H- /7 OCL 16	" Spruce (2)N42 ⁰ E-14 lks (9.24°)	
Sept.1967 - LCRC by G.G. S (MDOT) - Culv & In line	lattery, PE#3694 - (On with fac E & W - (5)S	File at Reg. of Deeds	one MKF (4)5426W-20.0"-4" Cone Mc) - Fnd Cone Mon - 5' E of Rd C.L)S60 ⁶ E-39.72'- 5" Birch - (7)S60°	& 7' S of C.M.P
			d - Fnd Conc Mon - Same Witnesses onc Mon - No Witnesses - Field No	
June 1996 - ACT 132 by L.G.	• Beauregard. PS#18654	-(Surveyor for Scott	Eng)-Rec L.10004, Pgs.358-359-Ex	st Conc Mon
	1			
B. Description of corner evide	ence found and/or method	applied in restoring or reesta	ablishing corner:	A CONTROL OF
-5 - CORNER COMMON TO SECT	TIONS 8, 9, 16 & 17		### ##################################	FREDERICK \
Fnd . 5" Conc Mon - (1-{	
Witnesses - Fnd Rec 5			\$ 6, \$	SURVEYOR No.
			LICENT	25852
				OPOFESSIONAL AND
			•	OFESSION AND
HIS CORNER APPROVED BY COUL	NTY PEER REVIEW ON JUL	Y 18, 2000, AS THE BES	T AVAILABLE EVIDENCE OF THE RE-ES	STABLISHMENT OF TH
RIGINAL CORNER.				
C. Description of manument to	or corner and assessed	manufic to the second s		
 C. Description of monument fo 5 - CORNER COMMON TO SECT 	TONS 8, 9, 16 & 17	stabilished to perpetuate loc	ating the position of the corner:	
		Re-Mon Cap on Fnd 5" C	one Men	
Corner Is ±5' E of (C.L. N-S Grav Rd. (Hos	sier Rd.) & ±7' S of C	one mon. .M.P. Culv & ±58° S of E-W Pwr L1	ine.

(Wit #8) - EASI - 33.30' (R-33.0') - Fnd 1/2" iron 0.5' E of Sti Fnc Post (Wit #6) - S60°E ±39' (R-39.72') - Fnd Birch Stump * \$35°E - 57.98' - Set S&T W side 5" Tamarack

(Wit #5) - S15°E - 61.73' - Fnd Spk in 10" Dead Tamarack (Wit #7) - S55°W (R-S60°W) - 47.35' (R-47.51') - Set S&T above fnd MSHD Tag - SE side Pwr Pole (N-S Pwr Line) (Wit #8) - WEST - 33.02' (R-33.0') - Fnd 1/2" Iron * N55°W - 79.10' - Set S&T SW side Pwr Pole #A6375 (E-W Pwr Lin

Typical Wit Set - 16-D Spk & Plastic ID Tag #25852

Date __ October 30, 2000

Signed by <u>Frederick</u> 4. Surveyor's Michigan License No.

MUPPROVED BY PEER GROUP