## SURVEY & REMONUMENTATION

JAN 2 2 2001

## **Montmorency County Remonumentation**

iher	OOO	1	2	Page	042	Ĭ
.i.uer	A.A.A.	4	-	Laaa		

LAND CORNER RECORDATION CERTIFICATE
Filling Requirement of Act 74, Mich. P.A. 1970

For corners in	1
MONTMORENCY Located In: BRILEY Corner Code #  (County)  1. Public Land Survey T 30NR 2E E-8	STATE OF MICHIGAN MONTMORENCY COUNTY Recorded & Filed
TR TR	11-13-2000 13:34:22
T R  2. Property Controlling S T R in Section S T R  3. Miscellaneous S T R	TERESA WALKER REGISTER OF DEEDS
Property in Sec. S TR	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	
5. Private Claims  I, FREDERICK J. KING , in a field survey on APRIL 3 , 2000 do hereby state to requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above conformance with regulations and rules therefore as required in the current manual of survey instructic United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Lat that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monifective of the corner points mentioned in lines 3.	e were in sins of the wand /or 619 17 16 15 14 13- unented, 7
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.	8 -19 -20 -21 -22 -23 -24 - 9 -10 -30 -29 -28 -27 -26 -25 - 11 -10 -30 -29 -28 -27 -26 -25 -
A. Description of original monument and accessories and/or subsequent restoration:  E-8 - 1/4 CORNER COMMON TO SECTIONS 20 & 21  June 1840 - Orig Post set by Lewis Clason, DS -(1)N66 E-23 iks(15.18*) 10 1941 - 2½" Conc Mon set by Frank Smith, PS#754 -(3)N4594-50.0*-4" Conc May 1974 - Act 132 by D.E. Porter, PS#15410 - Rec. L.1, Pg. 541 - Fnd Conc May 1974 - LCRC by D.E. Porter, PS#15410 - Rec. L. 1, Pg. 98 - Fnd Conc May 1974 - Witnesses furnished by D.E. Porter, PS#15410 - Not Recorded - 8 (4)S45°E-50.0*-Conc Mon (5)N45°E-42.29*-Fnc Corresponded - 1978 - Act 132 by D.E. Marlatt, PS#18660 - Rec. L.2, pg. 400 - No Cormay 1978 - Act 132 by D.E. Marlatt, PS#18660 - Rec. L.2, Pg. 513 - Fnd Mon 1978 - Act 132 by D.E. Beauregard, PS#18654 - (Surveyor for Scott Eng. (3)N45°W-50.0*-4" Mon-(4)S45°E-50.0*-4" Mon-(6)N65°E-37.48*-Fnc B. Description of corner evidence found and/or method applied in restoring or reestablis E-8 - 1/4 CORNER COMMON TO SECTIONS 20 & 21  Fnd 5" Conc Mon (Rec as 2 1/2")  Witnesses - Fnd Rec. 3,4 & 7  THIS CORNER APPROVED BY COUNTY PEER REVIEW ON JULY 18, 2000, AS THE BEST AN ORIGINAL CORNER.	c Mkr (4)545°E-50.0°-4"Conc Mkr.  Mon (3)N45°W-50.0°-Conc Mon (4)S45°E-50.0°-Con  on - No Witnesses Find Conc Mon (3)N45°W-50.0°-Conc Mon  Desc. No Witnesses 1 - Witnesses 3 &4 - Rec L.3, Pgs 429-430 - Exist Conc Mon  Cor-(7)WEST-33.62'-Fine Cor  shing corner:  FREDERICK J. KING  PROFESSIONAL SURVEYOR  No. 25852
C. Description of monument for corner and accessories established to perpetuate locatin E-8 - 1/4 CORNER COMMON TO SECTIONS 20 & 21  Placed 3 1/4" Aluminum Montmornecy County Re-Mon Cap on Fnd 5" Conc Corner is ±9' N of C.L. N-S Grav Rd (Hossier Rd.) & ±2' S of E-W Fel N85 E - 38.35' - Set S&T + N side Fnc Cor Post * EAST 33.02' - Fnd (Wit #4) - S45°E - 49.92' (R-50.0') - Fnd Rec. 4" Conc Mon (Wit #7) - N85°W (R-West) - 32.25' (R-32.62') - Set S&T - S side Fnd (Wit #3) - N45°W - 49.85' - (R-50.0') - Fnd Rec. 4" Conc Mon * N25 Typical Wit Set = 16-D Spike & Plastic ID Tag #25852	Mon nces. * N45 <sup>0</sup> E - 46.59' - Set S&T - SE sd 10" R. d I&C #18660 c Cor Post
Signed by Andruck J. Kmg Date	October 30, 2000 L.B.B.
Surveyor's Michigan License No 25852	