

# SURVEY & REMONUMENTATION

JAN 22 2001

Liber 00012 Page 0410

SECTION

## MONTMORENCY COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Located in:

Montmorency  
(County)

Briley  
(Township)

Corner Code #

1. Public Land Survey

T 30N R 2E

E-12

2. Property Controlling  
In Section

S  
S

T  
T

3. Miscellaneous  
Property in Sec.

S  
S

T  
T

4. Lot No. , Recorded Plat

5. Private Claims

STATE OF MICHIGAN  
MONTMORENCY COUNTY  
Recorded & Filed

10-27-2000 11:56:26

TERESA WALKER  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Larry G. Beauregard, in a field survey on MARCH, 20 00, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules thereof as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2												
3												
4												
5												
6												
7												
8												
9												
10												
11												
12												
13												

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:  
E-12 1/4 Corner between Sections 32 & 33.

1840 Lewis Clason, D.S. Set Qr. Sec. Post. Wit's mkd. (Spr. Pine 7" N34W 28 lks.) (Do. 6" S41E 30lks.)

Date & Surveyor unknown. Set 1/2" pipe with elbow 45'± West of Co. Rd. C/L. Wit's mkd. (S60W 4.19' 9" J. Pine.)

1942 Frank N. Smith RLS #754, field notes indicate he was on the line between Sec. 32 & 33. No mention of corner fnd., set or wit's mkd.

1973 Delmer E. Porter P.S. #15410 fnd. and accepted 1/2" pipe with elbow at Cor. 45'± West of Co. Rd. C/L in a sectional divisional survey of Sec. 32. Filed Act #132 Rec. L.1, P.280, & Filed LCRC Rec. L.1, P.50. Wit's mkd & fnd. on each (S60W 4.19' 9" J. Pine O.W.) (N35W 56.10' S.E. Cor. Hse.) (N89W 18.58' J. Pine).

1973 Delmer E. Porter P.S. #15410 fnd. 1/2" pipe with elbow & wit's in a survey in Sec. 33. Filed Act #132 Rec. L.1, P.307, & Re-filed same Act #132, in 1983 Rec. L.3, P.177. No new wit's mkd.

1982 Donald E. Mariatt P.S. #18660 fnd. & accepted 1/2" pipe with elbow & two Rec. wit's by Porter, in a survey in Sec. 33. Filed Act #132 Rec. L.3, P.206. No new wit's mkd.

1995 Larry G. Beauregard P.S. #18654 (Surveyor for Scott Assco., Inc.) fnd. & accepted 1/2" pipe with elbow & wit's by Porter, in a survey in Sec. 33. Filed Act #132 Rec. L.10004, P.0253. No new wit's mkd.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

March 2000: Fnd. 1/2" pipe with elbow & wit's by Porter, 45'± West of Co. Rd. C/L. Re-placed pipe with 4" x 36" concrete monument with a 3/4" aluminum Re-mon. cap.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-12 1/4 Corner between Sections 32 & 33

4" x 36" concrete monument with a 3/4" aluminum Mont. Co. Re-mon. cap.

Accepted as the best available evidence of the position of the original corner.

Accepted by the peer group on July 18, 2000.


N45°W 42.45' SE Cor. Conc. Fig.

S87°E 93.40' 20" Oak

S69°W 47.10' 5" Oak

S12°W 64.51' 13" J. Pine

Placed 60d penny spike & P.S. tag #18654 (typ).



APPROVED BY  
PEER GROUP

JUL 18 00

L.G.B.

Signed by Larry G. Beauregard

Date 10-27-00

Surveyor's Michigan License No. 18654

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1995