

SURVEY & REMONUMENTATION

JAN 2 2001

Montmorency County Remonumentation

Liber 00012 Page 0428

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MONTMORENCY
(County)

Located In: BRILEY Corner Code #

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

11-13-2000 13:34:32

TERESA WALKER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land Survey T_{30N} R_{2E} F-5
T₁ R₁
T₁ R₁
T₁ R₁
2. Property Controlling S₁ T₁ R₁
in Section S₁ T₁ R₁
3. Miscellaneous S₁ T₁ R₁
Property in Sec. S₁ T₁ R₁

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, FREDERICK J. KING, in a field survey on APRIL 6, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	

A. Description of original monument and accessories and/or subsequent restoration:

F-5 - 1/4 CORNER COMMON TO SECTIONS 9 & 16

June 1840 - Orig Post set by Lewis Clason, DS - (1)S28°W-19 lks(12.54') 11" Beech (2)N45°E-45 lks (29.70') 7" Maple- Pg.42
Dec. 1944 - Frank Smith, PS#754 - Notes - Iron Pipe (3)S57°W-9.7'-18" Elm (4)N51°W-65.3'-8" Ironwood - Info obtained from L.G. Beauregard, PS#18654 - (5)N33°W-89.6'-22" Elm
May 1967 - LCRC by G.G. Slattery, PE#3694 - (On File at Reg of Deeds) - Fnd 1 1/4" Pipe & Raised with 5/8" Iron Rod - ± 25' of C.L. traveled Rd. - ± 38' E of Rd Tang to N ± 7" S of Rd Tang to E. (6)N20°E-51.50'-11" Maple (3)S60°W-9.91'-29" Elm (4)N52°W-65.48'-11" Ironwood.
May 1967 - Witnesses furnished by D.E. Porter, PS#15410 - Not Recorded - Same Info as G.G. Slattery LCRC
Oct. 1974 - LCRC by D.E. Marlatt, PS#18660 - Rec. L.1, Pg. 142 - Fnd 1 1/4" Pipe (3)S60°W-9.91'-29" Elm (4)N52°W-65.48'-11" Ironwood.
Oct. 1974 - Act 132 by D.E. Marlatt, PS#18660 - Rec. L.2, Pg. 77 - Fnd 1" Pipe- No Witnesses.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-5 - 1/4 CORNER COMMON TO SECTIONS 9 & 16

Fnd Rec. 1-1/4" Pipe with 3/4" Bar Inside
Witnesses - Fnd Rec. 4 & 6



THIS CORNER APPROVED BY COUNTY PEER REVIEW ON JULY 18, 2000, AS THE BEST AVAILABLE EVIDENCE OF THE RE-ESTABLISHMENT OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-5 - 1/4 CORNER COMMON TO SECTIONS 9 & 16

Placed 3 1/4" Aluminum Montmorency County Re-Mon Cap on Fnd 3/4" Bar Inside 1 1/4" Pipe.
Corner Is 0.3' W of Fnc Cor Post & ± 36' E of C.L. Grav. Rd. to N & ± 14' S of C.L. Grav Rd. to E.
N20°E - ± 51' - (R-51.50') - Fnd Maple Stump (Wit #6)
N50°E - 64.73' - Set S&T - Above Fnd Spk - NW side 24" Beech * EAST - 0.33' - Set S&T - W side Fnc Cor Post
S75°W - 12.09' - NE Cor of GTE Box #L511-5
(Wit #4) - N52°W (R-N51°W & N52°W) - 64.98' (R-65.3' & 65.49') - Set S&T - NE side 15" Ironwood

Typical Wit Set = 16-D Spk & Plastic ID Tag #25852

APPROVED BY
PEER GROUP

Signed by Frederick J. King

Date October 30, 2000

Surveyor's Michigan License No. 25852

JUL 18 00

L.S.B.