

# SURVEY & REMONUMENTATION

JAN 22 2001

## Montmorency County Remonumentation

### SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

Liber 00012 Page 0429

For corners in

MONTMORENCY  
(County)

Located In: BRILEY Corner Code #

- |                                    |   |     |
|------------------------------------|---|-----|
| 1. Public Land Survey              | T <u>30</u> N R <u>2E</u>                 | F-7 |
|                                    | T <u>    </u> R <u>    </u>               |     |
|                                    | T <u>    </u> R <u>    </u>               |     |
|                                    | T <u>    </u> R <u>    </u>               |     |
| 2. Property Controlling in Section | S <u>    </u> T <u>    </u> R <u>    </u> |     |
|                                    | S <u>    </u> T <u>    </u> R <u>    </u> |     |
| 3. Miscellaneous                   | S <u>    </u> T <u>    </u> R <u>    </u> |     |
| Property in Sec.                   | S <u>    </u> T <u>    </u> R <u>    </u> |     |

STATE OF MICHIGAN  
MONTMORENCY COUNTY  
Recorded & Filed

11-13-2000 13:34:50

TERESA WALKER  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, FREDERICK J. KING, in a field survey on APRIL 6, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6	5			4		3		2		1	
3												
4	7	8			9		10		11		12	
5												
6	18	17			16		15		14		13	
7												
8	19	20			21		22		23		24	
9												
10	30	29			28		27		26		25	
11												
12	31	32			33		34		35		36	
13												

#### A. Description of original monument and accessories and/or subsequent restoration:

F-7 - 1/4 CORNER COMMON TO SECTIONS 16 & 21

June 1840 - Orig Post set by Lewis Clason, DS - (1)S12°E-38 lks (25.08') 20" Beech (2)N66°W-34 lks (22.44') 18" Beech Pgs 449 450

1941 - 2 1/2" Conc Mon set by Frank Smith, PS#754 - Info obtained from L.G. Beauregard, PS#18654 - (3)N45°E-50.0'- 4" Conc Mkr. (4)S45°E- 50.0'- 4" Conc Mkr.

No Rec. LCRC Fnd

No Rec. Act 132 Fnd

#### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-7 - 1/4 CORNER COMMON TO SECTIONS 16 & 21

Fnd 5" Conc Mon (Rec. as 2 1/2")

Witnesses - Fnd Rec. 3 & 4



THIS CORNER APPROVED BY COUNTY PEER REVIEW ON JULY 18, 2000. AS THE BEST AVAILABLE EVIDENCE OF THE RE-ESTABLISHMENT OF THE ORIGINAL CORNER.

#### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-7 - 1/4 CORNER COMMON TO SECTIONS 16 & 21

Placed 3 1/4" Aluminum Montmorency County Re-Mon Cap on Fnd 5" Conc Mon.  
Corner is in N-S Fnc & in Line with Fnc to E @ E edge of Field - Steel Post Alongside.

NORTH - 6.51' - Set S&T above Fnd Spk - E side 30" Twin Maple.

(Wit #3) - N35°E (R-N45°E) - 49.96' (R-50.0') - Fnd 4" Conc Mon. \* N65°E - 12.76' - Set S&T above Fnd Spk - NW sd 8" Maple. \* S80°E - 11.65' - Set S&T above Fnd Spk - N side 6" Maple

(Wit #4) - S45°E - 49.97' - Fnd 4" Conc Mon. \* S25°E - 8.31' - Set S&T above Fnd spk - E side 12" Maple (R-50.0')

Typical Witness Set = 16-D Spk & Plastic ID Tag #25852

APPROVED BY  
PEER GROUP

Signed by Frederick J. King  
Surveyor's Michigan License No. 25852

Date October 30, 2000

JUL 18 00

*J.L.B.*