

SURVEY & REMONUMENTATION

JAN 22 2001

Montmorency County Remonumentation

Liber 00012 Page 0448

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>MONTMORENCY</u> (County)	Located In: BRILEY TWP.	Corner Code # G-4
1. Public Land Survey	T 30N R 2E	G-4
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

12-05-2000 10:07:50

TERESA WALKER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, DONALD E MARLATT, in a field survey on MAV 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L
2	6	5	4	3	2	1					
3											
4	7	8	9	10	11	12					
5											
6	18	17	16	15	14	13					
7											
8	19	20	21	22	23	24					
9											
10	30	29	28	27	26	25					
11											
12	31	32	33	34	35	36					
13											

A. Description of original monument and accessories and/or subsequent restoration:

G-4 1/4 CORNER COMMON TO SECTIONS 9 & 10.
G.L.O. COR. SET BY LEWIS CLASON IN APR. 1840. Hd MAPLE 30" S36°W 10 L., BEECH 10" N51°E 12 L.
COUNTY ROAD COMMISSION NOTES: 1961. 1 1/2" IRON SHAFT. NORTH 36.42' 2" HUB, S47°W 38.02' T. POLE, S68°E 105.77' T. POLE.
G.G. SLATTERY P.E. 9/67 MSHD SURVEY CREW CHIEF FOUND 1 1/2" IRON ROD 2" BELOW SURFACE AND 1' SOUTH OF PAV'T C/L. N65°W 68.27' CHISELED "X" ON TOP OF EAST END OF 12" CMP, S 5°W 26.42' 4" ROAD SIGN POST, S50°W 38' T. POLE.
D.E. MARLATT P.S.# 18660 ACT 132 DATED 5/ 5/77. FOUND 1 1/2" ROD. S 5°W 26.42' ROAD SIGN, S50°W 38.0' T. POLE.
D.E. MARLATT P.S. FILED ACT 132 DATED 4/10/83 RECORDED IN L. 3, P. 200. FOUND 1 1/2" ROD. N65°W 68.27' "X" ON EAST END OF CMP, S50°W 38.0' T. POLE.
L.G. BEAUREGARD P.S.#18654 FILE ACT 132 DATED 3/10/88 RECORDED IN L. 3, P. 431. FOUND 1 1/2" ROD(R) N65°W 68.27' "X" ON EAST END OF 12" DR. CMP(R) S 5°W 26.42' ROAD SIGN POST(R).
CLIFF LINDGREN P.S.#14098 FILED ACT 74 DATED 4-14-96 RECORDED IN L.1, P. 522. FOUND 1" IRON ROD 1' SOUTH OF M-32 C/L. DISTANCE BETWEEN G-4 & F-4 CHECKS WITH 1967 MSHD SURVEY. 1967 WIT. FOUND 1 1/2" IRON ROD 1'S OF M-32 C/L. N65°W 68.27' "X" ON TOP OF EAST END OF 12" DR. CMP, S 5°W 26.42' 4" ROAD SIGN POST, S50°W 38.0' T. POLE. AFTER CONSTR. FOUND 1" ROD IN MON. BOX. N55°W 103.85' E. GATE POST, N44°E 49.57' 12" CLUMP OF CEDARS, S66°E 108.84' WOOD POST, N61°E 54.90' 4" ELM. (2' SOUTH OF M-32 C/L).

B. Description of cor. evidence found and/or method applied in restoring or reestablishing cor.
G-4 FOUND 1 1/4" BAR IN MON. BOX 2' SOUTH OF C/L. N55°W 103.85' E. GATE POST. R., N44°E. 49.57' 12" CLUMP OF CEDARS. R., N61°E 54.9' 4" ELM. R., S 5°W 33' 1/2" ROD.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
G-4 1/4 COR. COMMON TO SECTIONS 9 & 10.

PLACED 1/2" ROD & REMON CAP IN MON. BOX, SAID CAP BEING OVER 1 1/4" BAR.
N60°E 6" ELM 54.82'
N38°W 4" ELM 41.85'
S 5°W 33' 1/2" ROD
S 30°E NORTH SIGN POST 35.85'

WITNESSES MARKED WITH 40 PENNY SPIKES AND P.S. TAGS #18660. L.H.B.
APPROVED BY PEER GROUP ON JULY 18, 2000 AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

Signed by Donald E Marlatt
Surveyor's Michigan License No. 18660

Date 12/4/2000

