

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Montmorency Located In Corner Code #  
(County)

1. Public Land Survey T R  
T R  
2. Property Controlling in Section S 29 T 30N R 2E 1  
S 29 T 30N R 2E 2  
3. Miscellaneous Property in Section S T R  
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on February 26, 2001 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1-Donald E. Marlatt R.L.S. 18660 1982 Cert. of Survey  
"1/8 corner found Monument" Wit: S45°E 12" Maple 15.3',  
S10°W 13" J. Pine 17.7'

2-Delmer E. Porter L.S. #15410 LCRC Liber 1, Page 108 set  
1/2" rod by single proportion Wit: N80°E 3.03' 1 1/2" pipe,  
N80°E 24.55' 6" Aspen, N70°W 22.56' 6" Aspen.

Donald E. Marlatt R.L.S. #18660 Jan 1990 Cert. of Survey  
Found 1/2" rod and cap #15410 Wit: N75°W 7" Poplar 17.45',  
N45°W 7" Poplar 22.53', S50°W 4" Balsam 33.3'.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

1- Found concrete monument

2- Found 1/2" rod

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1- Found concrete monument

Wit: 20" Cedar S80°W 21.41'  
16" Cedar S40°W 17.26'  
6" Spruce N55°E 19.97'  
7" Spruce N18°E 18.76'

2- Set 5/8" X 32" Rerod with P.S. cap #33981

Wit: 5" Balsam S57°W 33.23'  
3" Balsam N15°W 20.22'  
P.Pole N51°E 30.89'  
6" Spruce S58°E 67.69'

Signed by:

Carl T. Kiiskila

Date:

2-7-02

Surveyor's Michigan License No.:

33981

