

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Montmorency

(County)

Located In

Corner Code #

1. Public Land Survey	T		R	
	T		R	
2. Property Controlling in Section	S 33	T 30N	R 2E	11
	S 33	T 30N	R 2E	12
3. Miscellaneous Property in Section	S	T	R	
	S	T	R	

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on April 30, 2001 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

11-Donald Marlatt RLS #18660 Aug 1982 set 1/2" rod and P.S. cap
Wit: N85°W 7" W. Pine 16.3', N30°W 5" Maple 15.05'

12-Donald Marlatt R.L.S. #18660 Avg. 1987 cert. of survey
Liber 3 Page 206 set 1/2" rod and cap wit: S10°E 8" Jack Pine 38.9', S60°E 11" Jack Pine 13.7', N05°E 7" Cherry 60.22'.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

11- Found 1/2" capped iron rod Marlatt L.S. #18660

12- Found 1/2" rod fitting Donald Marlatt distances North and South well.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

11-Found 1/2" capped rod Marlatt L.S. #18660

Wit: 10" Red Pine S68°E 23.28'
5" Maple N23°E 16.06'
10" White Pine N81°W 16.21'
5" Maple S48W 31.59'
Carsonite post North 1'±

12-Set 5/8" x 32" rerod with P.S. cap #33981

Wit: 6" Jack Pine N34°W 36.93'
14" Jack Pine S65°W 54.51'
30" Oak S24°E 99.11'
5" Jack Pine N77°E 63.86'

Signed by:

Carl T. Kiiskila

Date:

2-7-02

Surveyor's Michigan License No.:

33981

