

Montmorency County Remonumentation

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

09-27-1996 13:27:09

For corners in

Montmorency
(County)

Located In:
Rust Township

Corner Code ##

A. PANGAN-MCELROY
REGISTER OF DEEDS

1. Public Land Survey

T 30N R 4E

C-1

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Liber 00012 Page 0201

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Larry G. Beauregard, in a field survey on April, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-1 Section corner common to Sec's. 5 & 6.

1840 - Lewis Clawson D.S. intersected 3rd. correction line 81.13 ch's East of Twp. corner and set post.
No witnesses marked.

1982 - Kenneth J. Ostling RLS # 10068 DNR surveyor set std. DNR corner at U.S. record measurement from S 1/4 Section 31, as reestablished. No previous corner evident, then filed LCRC Rec. L. 1, P. 330. Wit's marked:
(S 29° W 17.7' 9" W. Oak) (N 69° E 5.1' 5" Oak).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found DNR std. corner in good condition (4" aluminum cap on 1" x 3' pipe) with DNR post along side and witnesses mentioned above.

SURVEY &
REMONUMENTATION

MAY 22 1997

COMMISSION

APPROVED BY
PEER GROUP

JUN 07 96

L.G.B.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-1 Section corner common to Sec's 5 & 6

4" aluminum cap on 1" x 3' pipe. Accepted as a careful and faithful establishment of the position of the of the corner. Approved by the Peer Group on June 7, 1996.


N 69° E 5.1' 8" Oak (R)

S 29° W 17.7' 14" W. Oak (R)

N 30° W 18.55' 5" Maple

N 13° E 36.28' 6" Maple

Placed 60d penny spike, P.S tag # 18654 & blaze.. (Typ.)



Signed by

Larry G. Beauregard

Date

9-24-96

Surveyor's Michigan License No.

18654