## I AND CORNER RECORDATION CERTIFICATE

For Corners in:	Filing Requir	rement of Act 74,	Mich. PA 1970	Instrument 201100047920	Liber Page 1 750
Montmorency (County)	Located In	Corner Code #	i	201100047920 Filed for Record	l in
1. Public Land Survey	T R	<del>.</del>		MONTMORENCY COUNTERESA WALKER, F 08-18-2011 At 09	REGISTER OF DEEDS
2. Property Controlling in Section S 3 S 3	T 31N R 1E T 31N R 1E	6 7		CAND CORNER	14.00 ge 750 - 750
3. Miscellaneous Property in Section S S S	T R		Res	gister of Deeds Stamp & I	File Number
4. Lot No: Record	ed Plat:		- A B C	DEFGHI	J K L M
5. Private Claims:			_ 2 6	5 - 4 - 3	2 1
1, <u>Carl T. Kiiskila</u> , in a field survey requirements of PA 74, Michigan PA and 2 above were in conformance withe current manual of survey instruinterior, Bureau of Land Management corner points mentioned in lines 3, 4 of the Michigan Board of Land Suestablished, re-established, monument	of 1970, the corner points ith regulations and rules the ctions of the United State tor by a decree of a Court and 5 above were in confourveyors or by a Decree	mentioned in lines 1 erefore as required in as Department of the of Law and/or that the rmance with the rules of a Court of Law;	5 18 7	-17 -16 -15	1113
NOTE: Not more than 2 corners, all in the same town and range, me be recorded on this certificate.			10 -30	29 28 27	26——25—
ei			11 12 -31 13	32 33 34	3536
A. Description of original monume	ent and accessories and	l/or subsequent rest	oration:		
6 - NE 1/16 corner, section 3, T31N,R01E		<u>7</u> -N	7-N 1/16 corner, comm. to sections 2 & 3, T31N,R01E		
None.		None.			
B. Description of corner evidence	e found and/or method a	applies in restoring o	or re-establishing co	orner:	
6 - NE 1/16 corner, section 3, T31N,R01E			7-N 1/16 corner, comm. to sections 2 & 3, T31N,R01E		
Set stamped 2" dia. aluminum cap on 5/8" x 34" rebar per standard BLM procedure. Found no other evidence to dispute the location for this corner.		ocation for d	Set stamped 2" dia. aluminum cap on 5/8" x 34" rebar by prorated distance to GLO measurement along the E. line of section 3. Found no other evidence to dispute the location for this corner.		

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 6 NE 1/16 corner, section 3, T31N,R01E

2" dia, stamped aluminum cap on 5/8"x 34" rebar.

Witnesses:

N37°E 34.75' to set N&T on NW side 22&24" Twin W. Pine S51°E 52.46' to set N&T on SW side 16" R. Pine S13°W 38.70' to set N&T on SE side 3" W. Pine N59°W 67.32' to set N&T on N side 20" R. Pine South 71' to centerline E-W 2-track Set blue carsonite post w/ location tag 1' North.

33981 Surveyor's Michigan License No.:

7-N 1/16 corner, comm. to sections 2 & 3, T31N,R01E

2" dia. stamped aluminum cap on 5/8"x 34" rebar.

Witnesses:

N52°E 21.05' to set N&T on NW side 14" W. Pine S65°E 47.81' to set N&T on SW side 21" W. Pine South 21.70' to set N&T on E side 20" R. Pine N57°W 18.65' to set N&T on SW side 18" R. Pine Set blue carsonite post w/ location tag 1' North.

OF MICHIGAN CARL KHSKILA LAND SURVEYO No. 33981 SURVED LAND SURVE

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN 28, 1971

Revised May 14, 1975 Revised Jan. 1983 Revised Oct. 1995