MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_31... NR_2_E... T 31 NR 1 E

			MontmorencyCOUNIN
DESCRIPTION	OF	CORNER	Section Corner common to Sections 7,18,12,13
DESCRIPTION	OF	CORNER	MONUMENT_1" Pipe with 4" Brase cap
WITTNESSES	то	CORNER	13" Ceder - N_85 F - 15 Links
			10" Ceder - N 64 E - 70 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner had been previously located and perpetuated by Marcus Schaaf, Registered Land Surveyor, from original B.T.'s. One original B.T. still in place, in excellent condition.

Corner was placed and witnessed April 20, 1951.

SURVEYORS SEAL

SIGNED Sear C. Sede mater DATE 3/21/51 -