

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Montmorency</u> (County)	Located In:	Corner Code <u>≠</u>
1. Public Land Survey	T <u>31N</u> R <u>3E</u>	<u>B-2</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S <u>7</u> T <u>31N</u> R <u>3E</u>	<u>4</u>
	S <u>7</u> T <u>31N</u> R <u>3E</u>	<u>1</u>
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

I, Carl R. Johnson, in a field survey on October 4, 19 88, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- 4 - Set by standard survey procedure for subdividing a section.
 1 - Set single proportionately between $\frac{1}{4}$ corner and section corner.
 B-2 - Set corner at fence corner fence north and west. Fits close to GLO measurement east to section corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | |
|---|---|
| 4 - Center of NW $\frac{1}{4}$
Set 5/8" bar w/cap & cedar post
7" J. Pine N48°E 43.2'
10" Oak S51°E 9.9'
5" J. Pine S82°W 23.5'
Fence cor east 62.0' | 1 - W1/8 Cor on N. side
Set 5/8" bar w/cap & Cedar post
7" Maple N26°W 5.0'
6" J. Pine S77°W 33.5'
Fence Corner S83°E 16.0' |
| B-2 N $\frac{1}{4}$ Corner
Set D.N.R. Monument
14" J. Pine N22°E 80.1'
12" J. Pine S74°E 22.3'
10" Oak S5°W 112.7' | |

Signed by Carl R. Johnson
 Surveyor's Michigan License No. 30083

Date 8/7/89

