

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Montmorency

(County)

Located In

Corner Code #

| | | | | | |
|--------------------------------------|---|-----|---|-----|--------|
| 1. Public Land Survey | T | 31N | R | 3E | J-6 |
| | T | | R | | |
| 2. Property Controlling in Section | S | 21 | T | 31N | R 3E 8 |
| | S | | T | | |
| 3. Miscellaneous Property in Section | S | | T | | R |
| | S | | T | | R |

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on July 19, 2005 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

J-6 This corner position was not established during the original government survey.

8- This corner position was not established during the original government survey.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

J-6 Established the center of section 14 at the intersection of the North-South and the East-West quarter lines as per B.L.M. instructions for the subdivision of a section.

8- Established the Northwest corner of the Northeast quarter of the Southwest quarter of section 21 as per B.L.M instructions for the subdivision of a section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-6 Set a 5/8" X 32" rerod with P.S. cap #33981
 Wit: 15" Red Pine N80°E 60.69'
 10" Red Pine S70°E 66.59'
 7" Jack Pine S55°W 45.12'
 1/2" iron West 6.47'
 Fence Post w/ fence going N & W West 5.87'
 Carsonite Post North 1'±

8- Set 5/8" X 32" rerod with P.S. cap #33981
 Wit: 8" Oak N20°W 44.29'
 22" Oak N32°W 46.08'
 6" Cherry S46°E 29.65'
 5" Oak S78°W 29.90'
 N-S Fence West 4'±

Signed by:

Carl T Kiiskila

Date:

2/22/06

Surveyor's Michigan License No.:

33981

