

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

I, KENNETH J. OSTLING, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on APRIL 14,, 1982, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

B. (CONTINUED)

3-13 SET CORNER BY PROPORTIONATE MEASUREMENT BETWEEN SECTION CORNERS.

C. (CONTINUED)

B-13
SET DNR MONUMENT
6" MAPLE N10°E 3.4'
5" MAPLE S78°E 11.9'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

-13 SET CORNER BY SINGLE PROPORTIONATE MEASUREMENT BETWEEN THE SW OF SECTION 31 AND THE SE OF SECTION 32. A 1/2" IRON BAR SET ERRONEOUSLY BY MSHD IS ABOUT 46' SOUTH AND 66' EAST. NO U.S. EVIDENCE.

:-12 FOUND 1 1/4" PIPE AS ESTABLISHED IN A PREVIOUS SURVEY OF UNKNOWN ORIGIN. OLD LOCATION FOR MSHD CORNER (PREVIOUSLY REMOVED) WAS ABOUT 77' SE'LY.

-12 SET CORNER BY SINGLE PROPORTIONATE MEASUREMENT BETWEEN SECTION CORNERS. 1/2" PIPE SET ERRONEOUSLY BY MSHD IS ABOUT 33' SE'LY BUT WAS NOT SET FROM ERRONEOUS DATA BUT NOT REMOVED OR ADJUSTED.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<u>C-13</u>			<u>E-12</u>			<u>C-12</u>		
SET CABIN SPIKE IN			DNR MONUMENT			SET DNR MONUMENT		
CEDAR STUMP			7" BALSAM S77°E 20.0'			8" JACK PINE N54°W 22.6'		
14" CEDAR	S35°E	3.25'	20" ASPEN	N80°E	16.2'	6" JACK PINE	N87°E	13.4'
12" CEDAR	S75°W	4.5'	10" BALSAM	N60°E	46.4'	1/2" PIPE (MSHD)	S47°E	40.1'

SIGNED BY Wm. A. Kling DATE 11/1/54

SURVEYOR'S MICHIGAN REGISTRATION NO. #10068

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ MONTMORENCY COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET