

# Montmorency County Remonumentation

Libel 12 Page 65

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Montmorency (County)	Located in:	Corner Code #
1. Public Land Survey	T 31N R 4E	A-8
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

RECEIVED  
MONTMORENCY CITY  
REGISTERED  
DEC 28 9 06 AM '93  
A. PANCAN-METROY

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat  
5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Larry G. Beauregard in a field survey on August, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

### A. Description of original monument and accessories and/or subsequent restoration:

NOTE: THIS TWP. LINE IS A RESURVEYED LINE BY BURNHAM.

(A-8) GLO Post set by Hiram Burnham April 1850.

Wits: Dry Spruce Pine 6" N 57 $\frac{1}{2}$ ° W 55 links Dry Spruce Pine 5" S 60° W 22 links

Carl R. Johnson P.S. #30083 (DNR Surveyor) in April 1992 set 3/4" pipe & cap #30083 by S.P. Method. Carl didn't find any evidence of original corner or subsequent Survey. (Act 74 on file) Rec. L. 1, Page 474. Wits: (Jack Pine S 34° E 14.7') (Oak 8" N 33° E 22.2') (Jack Pine 6" S 61° W 17.8') (Center Line of Co. Rd. 29' East).

### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A-8) Fnd. witnesses, 3/4" pipe & cap #30083, 29'± West of Miller Creek Road.

(Placed 3" dia. Aluminum cap marked Montmorency Co. Re-Monumentation Corner on same.)



### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A-8)  $\frac{1}{4}$  Cor. Comm. to Sec's 19 & 24, T31N, R3E & T31N, R4E

3/4" pipe & Re-Mon. cap #18654. Accepted as a careful and faithful establishment of the position of the corner, approved by the Peer Group on September 24, 1993.

N 33° E 22.2' (R) to blaze, 22.6' to spike, 8" Oak (R) NBT  
N 45° W 11.2' (R) to blaze, 11.5' to spike, 6" Jack Pine (R) NBT  
S 61° W 17.8' (R) to blaze, 18.19' to spike, 6" Jack Pine (R) NBT  
S 34° E 14.7' (R) to blaze, 15.0' to spike, 6" Jack Pine (R) NBT  
(Placed 20 penny spike & P.S. tag #18654) (typ)

Signed by

Larry G. Beauregard

Date

12-27-93

Surveyor's Michigan License No.

18654