			ORDATION CERTIFIC					
For corners in	Filing R	equirement o	f Act 74, Mich. P.A. 1	1970				
MONTMORENCY	Located In:	Corner Code	#					
(County)								
1. Public Land Survey	T32N R 2E	E-9.	E-8					
	<u>TR</u>							
	TR				*	,		
2. Property Controlling	TR S TR	-						
in Section	S TR S TR	-						
3. Miscellaneous	S TR							
Property in Sec.	S TR			Red	ister of De	eds Stamp	& File Nu	mher
						ous oranip	<u></u>	
4. Lot No, Record	ded Plat							
5. Private Claims				A B	C D E	F G H	I J F	(L
				2 - 6	5	-4		<u></u>
CARL KIISKILA	JUN	E 8 9	7	3				<u> </u>
	, in a field survey on			r 4 - 7		_ 910	111	12_
requirements of P.A. 74, Michiga	n P.A. of 1970, the corner poi	ints mentioned in	lines 1 and 2 above were in	1 _	ĬĬ			l i
conformance with regulations and								
United States Department of the lithat the corner points mentioned				, " "		1615		13-
Board of Land Surveyors or by	a Decree of a Court of Lav			, 7				
recovered, found as expressed be	iow:			8 -19	20-	_2122	_ 23	24-
NOTE: Not more than 2 com	ers, all in the same town an	d range, may be	recorded	9	- - -		++-	\vdash
on this certificate.				10 30	29-	2827	26	-25-
				11	-			
	• •			12-31	32	3334	35	36-
				13				
A. Description of original mo	nument and accessories a	nd/or subseque	nt restoration:					
E-8			E-9			errest,		
					ا کاکنچو	OF MICH	Garage Contract of the Contrac	
(NO EVIDENCE OF G.L.O. CORNE					75th.	CARI		
AS CALLED OUT IN THE G.L.O.	LINE NUTES; UNLESS NUTED	IN TIFE "B"			<i>3</i> :	KIISKILA		
BELOW.)			•		1 *	LAND	*)
					4	SURVEYOR	:	! !
					3 5	No. 33981	. 5/	
					CEN	•••••	RIVERA	
B. Description of corner evid	ience found and/or method	d applied in rest	oring or reestablishing co	orner:	188	ED LAND S	متحمد	
		• •				MARKE	-	
E-8	or ore at cook littless b	V MAROUS	E-9	* /2* DIDE	UITU CONC	מארר אר רר	T NV	
REESTABLISHED THE W 1/4 COR			FOUND AND ACCEPTED A 1 MARCUS SCHAAF P.S. FROM					,
SCHAAF P.S. MONUMENT FALLS D	N N-5 SHOUTH WIKE FENCE.		пиксоб ослинг г.б. rkur FENCE 3' EAST. SMOOTH					
	•		FENGE 3 ENSI: SHOUTH	WINE FERGE	NUMMINU L	MUI INDII GC	MALIVE	
	•							
			•			-		
							, , , ,	
C. Description of monument	for corner and accessories	established to	perpetuate locating the p	osition of the	ne corner:			
J.								
E-8			E-9					
SET 1" x 32" IRON PIPE W/DNR	ALUMN. CAP. W/CARSONITE	POST	FOUND A 1 1/2" PIPE WIT	TH CONC. BA	SE			
JACK PINE 8" SO4" W 11.7			JACK PINE 2" S38°E	22.00				
JACK PINE 8" S38°E 43.9			JACK PINE 4" N76°E	7.29				
JACK PINE 8" N38°E 43.2		<u>;</u> ^	JACK PINE 3" N30°W	17.34				
JACK PINE 7" N34"H 38.8	1'		JACK PINE 2" S75°W	15.66				
PK NAIL WOODGATE N34°W 3.11			1/2" I.P. EAST 3.59'					
JACK PINE 5" S75°N 14.6	7'		ADDED A CARSONITE POST					
\mathcal{O}	O T Kisk	'L		P 7	0-97)		
Signed by	339	(Date	0 2	- /			
Currente Michigan License N	339	01						

Surveyor's Michigan License No._