

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T..32. NR..3 E..

----- Montmorency ----- COUNTY

DESCRIPTION OF CORNER .. 1/4 Corner common to Sections 20 and 21

DESCRIPTION OF CORNER MONUMENT 1" pipe with a 4" brass cap

WITNESSES TO CORNER 6" Elm N 45 E 78 links

..... 6" Maple S 5 W 51 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was established by proportionate measurement between section corners by Forestry Division survey crew while making a survey in this area. Government Hemlock all gone. Corner checks very good with stream south for latitude. Found an old post on the ground about 3 rods west of corner, but could not determine where it stood before removal and used for a hunter's seat.

Corner was placed and witnessed November 13, 1958.

SURVEYORS SEAL

SIGNED

REGISTERED LAND SURVEYOR

Kenneth J. Oetting

DATE 11/19/58