

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
MONTMORENCY  
(County)

Located In:

Corner Code #

1. Public Land Survey	T 32N R 3E	M-4, M-5
	T R	M-6
	T R	
	T R	
2. Property Controlling in Section	S 12 T R	14
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, CARL KIISKILA, in a field survey on AUGUST 27, 19 96,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law, established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-4

M-5

M-6

(NO EVIDENCE OF G.L.O. CORNER, B.T.'S, LINE TREES & TOPOGRAPHY,  
AS CALLED OUT IN THE G.L.O. LINE NOTES; UNLESS NOTED IN ITEM "B"  
BELOW.)

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-4

M-5

M-6

14

FOUND 2 1/2" SQUARE CEDAR POST  
SCRIBED "1/4 SEC" FOR E1/4 COR  
S-12. NORTH EDGE OF CEDAR  
BALSAW SWAMP IS 130' +/- NORTH.  
W1/4 COR S-7, T32N-R4E SET DNR  
MON IS S00 35' 11"E, 230.36'.  
CORNER FALLS UNDER N-S SMOOTH  
WIRE.

REESTABLISHED THE SE COR OF  
S-12 RECORD US GOVT. DISTANCE  
NORTH OF FD SW COR S-7,  
T32N-R4E AND ON LINE BETWEEN  
SAID SW S-7 & FD E1/4 COR  
S-12, T32N-R3E. SMOOTH WIRE TO  
SOUTH AND WEST. SW COR S-7,  
T32N-R4E, FD 1/2" REROD &  
REPLACED W/DNR MON, IS  
S00 35' 11"E, 284.46'.

REESTABLISHED THE E1/4 COR  
S-13 S.P. BETWEEN FD SE COR  
S-13 & REESTABLISHED NE COR  
S-13 & ON A STRAIGHT LINE  
BETWEEN SAID FD SE S-13 & FD  
NW COR S-18, T32N-R4E. CTR OF  
N-S WINDING SAND TRAIL (ON  
PRIVATE) IS 61' +/- WEST. N-S  
SINGLE STRAND OF SMOOTH WIRE  
ON TREES IS 5' +/- EAST.

ESTABLISHED THE NE COR OF THE  
FRL SE1/4 OF THE FRL SE1/4 OF  
S-12 PER STANDARD BLM  
INSTRUCTIONS.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-4

M-5

M-6

14

SET 1"x 32" IRON PIPE W/DNR  
ALUMN CAP & CEDAR POST.  
5" MAPLE S37°E 31.58'  
5" SPRUCE S53°W 15.87'  
5" SPRUCE N29°W 32.11'  
7" MAPLE N46°E 24.86'  
1W.PINE S47°E 20.12'  
1B" SPRUCE N12°W 12.01'

SET DNR MON & CEDAR POST.  
4" SPRUCE N43°W 34.14'  
4" MAPLE N36°E 22.19'  
3" MAPLE S70°E 14.18'  
6" CEDAR S09°W 25.09'  
FENCE COR POST N70°W 9.0'  
16" PINE STP S75°E 17.3'

SET DNR MON & CEDAR POST.  
8" MAPLE N70°W 31.3'  
10" MAPLE N30°W 38.3'  
6" MAPLE S10°W 19.7'  
7" MAPLE S50°W 40.0'  
W1/4 S-18, T32N-R4E, SET DNR  
MON IS S01°22'23"E 280.39'

SET 5/8"x 32" REROD W/PS CAP &  
ALUMN TAG ON FENCE COR POST,  
WIRE NORTH & WEST.  
6" SPRUCE NORTH 22.78'  
5" SPRUCE S88°E 18.16'  
8"W.BIRCH S30°E 10.82'  
6" MAPLE S55°W 11.56'

1 = OLD HIT.

Signed by Carl T. Kiiskila Date 2-27-97

Surveyor's Michigan License No. 33981