

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Montmorency

(County)

Located In

Vienna

Twp.

Corner Code #

1. Public Land Survey

T _____ R _____

T _____ R _____

2. Property Controlling
in Section

S 24 T 32N R 3E 8

S 24 T 32N R 3E 11

3. Miscellaneous
Property in Section

S _____ T _____ R _____

S _____ T _____ R _____

4. Lot No: _____

Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on March 1 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		6		5		4		3		2		1
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

8 - CW 1/16 Corner, Section 24, T32N,R3E

11 - SW 1/16 Corner, Section 24, T32N,R3E

None

None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

8 - CW 1/16 Corner, Section 24, T32N,R3E

11 - SW 1/16 Corner, Section 24, T32N,R3E

Set stamped 2" dia. aluminum cap on 5/8"x34" rebar per standard BLM procedure. Corner falls N60°W 30.8' of old fence post corner with remains of fence running South and West. Found no other evidence to dispute the location for the corner.

Set stamped 2" dia. aluminum cap on 5/8"x34" rebar per standard BLM procedure. Corner falls N69°W 33.3' of old fence post corner with remains of fence running North and East. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

8 - CW 1/16 Corner, Section 24, T32N,R3E

11 - SW 1/16 Corner, Section 24, T32N,R3E

Stamped 2" dia. aluminum cap on 5/8"x34" rebar

Stamped 2" dia. aluminum cap on 5/8"x34" rebar

Wit: N01°E 32.60' to set N&T on W side 4" R. Maple
S74°E 2.70' to set N&T on NW side 24" R. Oak
S07°W 23.15' to set N&T on E side 6" R. Maple
N66°W 13.83' to set N&T on N side 11" R. Oak
Set Blue Carsonite post w/location tag 2' North.

Wit: N64°E 63.31' to set N&T on N side 12" R. Pine
S86°E 66.64' to set N&T on N side 17" R. Pine
S57°W 52.86' to set N&T on S side 13" W. Pine
N02°W 32.91' to set N&T on W side 12" R. Oak
Set Blue Carsonite post w/location tag 1' North.

Carl T Kiiskila

Surveyor's Michigan License No.:

33981

3-25-10

