

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Montmorency
(County)

Located In
Vienna
Twp.

Corner Code #

1. Public Land Survey T R
T R
2. Property Controlling in Section S 24 T 32N R 3E 12
S 24 T 32N R 3E 13
3. Miscellaneous Property in Section S T R
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on February 18 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

12 - CS 1/16 Corner, Section 24, T32N,R3E

13 - SE 1/16 Corner, Section 24, T32N,R3E

None

None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

12 - CS 1/16 Corner, Section 24, T32N,R3E

13 - SE 1/16 Corner, Section 24, T32N,R3E

Set stamped 2" dia. aluminum cap on 5/8"x34" rebar per standard BLM procedure. Corner falls 50.5' South of E-W single strand wire. Found no other evidence to dispute the location for the corner.

Set stamped 2" dia. aluminum cap on 5/8"x34" rebar per standard BLM procedure. Corner falls 17.5' West of N-S single strand fence. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

12 - CS 1/16 Corner, Section 24, T32N,R3E

13 - SE 1/16 Corner, Section 24, T32N,R3E

Stamped 2" dia. aluminum cap on 5/8"x34" rebar

Stamped 2" dia. aluminum cap on 5/8"x34" rebar

Wit: N14°E 9.89' to set N&T on NW side 6" B. Spruce
S07°E 9.83' to set N&T on W side 6" S. Pine
S55°W 10.67' to set N&T on N side 7" S. Pine
N66°W 11.88' to set N&T on SW side 6" S. Pine
Set Blue Carsonite post w/location tag 1' North.

Wit: N62°E 14.86' to set N&T on N side 12" R. Maple
S31°E 37.56' to set N&T on E side 6" R. Maple
S45°W 37.87' to set N&T on NW side 9" R. Oak
N23°W 11.29' to set N&T on E side 9" R. Oak
Set Blue Carsonite post w/location tag 0.3' North.

Carl T. Kiiskila

Surveyor's Michigan License No.: 33981

3-25-10

