

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
MONTMORENCY

(County)

Located In:

Corner Code #

1. Public Land Survey

T 32N R 4E

A-5, B-5

T R

T R

T R

2. Property Controlling  
in Section

S 7 T R

15, 16

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, C.T. KIISKILA, in a field survey on NOVEMBER 3, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-5

B-5

16

(NO EVIDENCE OF G.L.O. CORNER, B.T.'S, LINE TREES & TOPOGRAPHY, AS CALLED OUT IN THE G.L.O. LINE NOTES; UNLESS NOTED IN ITEM "B" BELOW.)

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	13		14		15		16		17		18		
7													
8	19		20		21		22		23		24		
9													
10	25		26		27		28		29		30		
11													
12	31		32		33		34		35		36		
13													

15



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-5

B-5

16

15

FB & ACCEPTED 1/2" REROD FOR NW COR SEC 18. D. MARLATT'S PS# 18660, CERT OF SURVEY L.3, PG.582 SAYS "SET 1/2" REROD & CAP". WE FIT ALL 3 D. MARLATT WITS GOOD. SE COR S-12, T32N-R3E, SET DNR MON, IS N00°35'11"W 284.46'.

REESTAB'D N 1/4 COR OF SEC 18 PRORATED TO U.S. GLO RUN OUT BTM FB NW COR S-18 & REESTAB NE COR S-18. CTR OF TRAIL RD SW IS 24' N. TRAIL ALSO GOES NE THEN TURNS E'LY, 38' +/- NORTH OF CORNER.

ESTABLISHED NE COR OF NW 1/4 OF NE 1/4 S-18 PER STANDARD BLM INSTRUCTIONS.

ESTABLISHED THE SE COR OF THE FRL SE 1/4 OF FRL SW 1/4 OF SEC 7 PER STANDARD BLM INSTRUCTIONS (PRORATED TO GLO RUN OUT.)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-5

B-5

16

15

FB 1/2" REROD, REPLACED W/DNR MON & SET CED POST W/LOC TAG. 114" SPRUCE N08°E 18.84' 14" MAPLE N89°W 29.64' 110" MAPLE S21°W 45.57' 8" MAPLE S46°E 23.04' EAST 10'± TO N & S SMOOTH WIRE UPPER BLAZE & SIDE NAIL

SET DNR MON & CED POST. 4" MAPLE N83°E 7.51' 4" BIRCH S04°E 29.59' 2" R PINE N79°W 43.58' 2" W PINE N13°W 48.15'

SET CAPPED REROD & CED POST. 2" BALSAM N58°E 11.34' 5" TW OAK S59°W 8.22' 20" W PINE S10°W 37.03' 16" W PINE S11°E 35.19' CORNER APPROX 145' EAST OF EAST EDGE RYE FIELD

SET 5/8" X 32" REROD W/CAP & CED POST. 6" W PINE N02°W 6.46' 6" RED MAPLE S77°E 27.27' 4" WHITE PINE S11°W 36.46' 6" RED MAPLE N76°W 42.15' N 125' +/- TO E-W SMOOTH WIRE. UPPER BLAZE & SIDE NAILS.

OLD WITNESS BY D. MARLATT.

Signed by Carl T. Kiiskila

Date 2-27-97

Surveyor's Michigan License No. 33981