

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
MONTMORENCY
(County)

Located In:

Corner Code ~~77~~

1. Public Land Survey	T 32N R 4E	C-3, C-4
	T R	
	T R	
	T R	
2. Property Controlling in Section	S 7 T R	9, 14
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, CARL KIISKILA, in a field survey on JULY 18, 19 96,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-3

C-4

9

(NO EVIDENCE OF G.L.O. CORNER, B.T.'S, LINE TREES & TOPOGRAPHY,
AS CALLED OUT IN THE G.L.O. LINE NOTES; UNLESS NOTED IN ITEM "B"
BELOW.)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-3

C-4

9

14

FD AND ACCEPTED D.MARLATT,
P.S.#18660 IRON FOR NE COR OF
SEC. 7.

FD AND ACCEPTED D.MARLATT, PS
#18660, IRON FOR THE E1/4 COR
SEC. 7. CORNER AT WIRE
N-S-E(SINGLE SMOOTH STRAND).

ESTABLISHED THE SW COR OF E1/2
OF NE1/4 OF S-7 PER STANDARD
BLM PROCEDURE. FD D.MARLATT
IRON S83 18'W, 4.54'; COULD
NOT ACCEPT FOR PROPER CORNER.

FD PS, D.MARLATT SE COR OF
NE1/4 OF SE1/4 OF SEC. 7, COR
OF RECORD Li. 3, Pg. 582. A
SINGLE STRAND OF SMOOTH WIRE
ON TREES (10" TAMARACK AT COR)
RUNS N10 E & S64 E, IS N44 W,
8 FT.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-3

C-4

9

14

FOUND 1/2" x 18" REROD WITH
D.MARLATT PS CAP, SET DNR MON.
& SET CARSONITE POST.
10" OAK NORTH 43.30'
11" OAK N85°W 27.79'
10" OAK S18°W 40.73'
8" MAPLE S81°E 15.46'

FD CAPPED IRON & POST, PLACED
LOCATION TAG ON POST.
16" MAPLE S48°E 13.19'
14" OAK N46°E 18.27'
12" OAK N32°W 12.03'
4" MAPLE S63°W 9.83'

ALL TREES HAVE UPPER & LOWER
BLAZES WITH SIDE SPIKES.
= OLD HIT.

SET 5/8" x 32" REROD W/PS CAP &
CARSONITE POST.
8" OAK S70°E 46.93'
6" OAK SOUTH 28.91'
8" OAK S58°W 26.67'
10" OAK N08°E 10.61'
N-S SMOOTH WIRE WEST 43'

FD CAPPED IRON, SET CEDAR POST
18" CEDAR S12°W 17.26'
16" CEDAR S50°E 13.58'
14" CEDAR N50°W 35.31'
4" TAMARACK N61°E 7.48'

ALL TREES HAVE UPPER & LOWER
BLAZES WITH SIDE SPIKES.

= D.MARLATT WITS.

Signed by Carl T. Kiiskila 33981

Date 2-27-97

Surveyor's Michigan License No. _____

