

MAR 0 2 1999

NEWAYGO COUNTY REGISTER OF DEEDS

1998 Newaygo County Remonumentation Project LINDA M. BROWN

SECTION

LAND CORNER RECORDATION CERTIFICATES FEB 17 PM 3 37. FILING REQUIREMENT of Act 74, Mich. P.A. 1970

	· ······· · · · · · · · · · · · · · ·		4		
For corners in Newaygo (County)	Located in:	Corner Code #	Linda M.	Drown ;	
Public Land Survey	T <u>12N</u> R <u>13W</u> T R T R	D-7	vol. 2	193	
Property Controlling in Section Miscellaneous	T R R S T R R R R R R R R R R R R R R R				
Property in Sec.	STR	<u>Re</u>	egister of Deeds Stamp	& File Number	
4. Lot No, Reco	rded Plat		A B C D E F G 1	H I J K L M	
do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curr Department of the Interior, Bure Law and/or that the corner po conformance with the rules of Decree of a Court of Law, established the covered, found as expressed by		of 1970, the corner egulations and rules fithe United States decree of a Court of 5 above were in Surveyors or by a sed, re-monumented,	5 6 18 - 17 - 16 - 7 8 - 19 - 20 - 21 - 9	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	
Note: Not more than 4 or recorded on this of	corners, all in the same tovertificate.	wn and range, may be	10 30 29 28 11 12 31 32 33 -	+ + + + + + + + + + + + + + + + + + + +	
South One Quarter Corner,	Section 17, Garfield Township,	Newaygo County, Michigan.	13	<u> </u>	
A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:					
			John C. Brewster (County Surveyor) Book A Page 119 April 23, 1891		
8" Beech N10°W 19 Links			r. Stake with bottle and	old Iron.	
Newaygo County Road C Monument Box	ommission Sheet		/itness Book Page 152 58½ Links (38.61')#3 Links (60.72')#4		
Lyle S. Shepherd R.L.S. a County Surveyor's Witnes 18" Elm N00¼°W 83.3' # 8" Oak S70%°W 51.7' #6 Gas Pipe South 25' #7	ss Book Page 152 5	Patrick A. Salisbury F Consumers Power C Section 20, T12N R1	Company Section Break	onument box	
B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:					
surveys. The centerline of	th no monument inside. Use of the East and West bitumir 172 feet ± East. There is no gone.	nous road is 1 foot South a	and on line ± with fence	going South and	
C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:					
Removed monument box monument box as a substitute original corner.	x and set a 2¾" X 20" Harris stantial marker for the sectio	on cast iron monument m n corner and is accepted	arked "County Survey" as a careful and faithful	n new 8" diameter reestablishment of	
Power Pole S27°E 58.30 Power Pole N02°W 51.6 16" Ash N78°W 217.70' \$	602°E 80.95' Set spike with to Set spike with tag #22439 in Set spike with tag #22439 in	in East side of pole. in East side of pole. South side of tree.			
Signed by Norman L. Oc	an (), UNIV		tober 20, 1998		
Surveyor's Michigan License		Form approved by M	iongan State Board of Land S	urveyors, Jan 28, 1971 Revised May 14, 1975	
Approved by Peer Review Group Norman L. Ochs, County Repre			NORMAN	Revised Jan., 1983	
M. L.O.		**	L. OCHS *		

NORMAN L. OCHS LAND SURVEYOR

ED LAND