

SURVEY & REMONUMENTATION

MAY 28 1997

1996 Newaygo County Remonumentation Project

NEWAYGO COUNTY
REGISTER OF DEEDS
LINDA M. BROWN

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'97 FEB 12 PM 4 45

For corners in
Newaygo
(County)

Located in: Corner Code #

1. Public Land Survey T 12N R 13W L-11

2. Property Controlling S T R

in Section S T R

3. Miscellaneous S T R

Property in Sec. S T R

4. Lot No. , Recorded Plat

5. Private Claims

Linda M. Brown

VOL. 1 PAGE 229

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

I, Norman L. Ochs, in a field survey on October 3, 1996, do hereby certify that under requirements of P. A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Note: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

North One Quarter Corner, Section 36, Garfield Township, Newaygo County, Michigan

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. J.H. Mullett 1839
10" Beech S53°E 29 Links (19.14') #1
8" Beech N32°W 30 Links (19.80') #2

Ralph A. Smith R.L.S. #3421
Book 81 Page 10 ± April 1931
8" White Oak for corner

Winfield S. Merrill (County Surveyor)
Book B Page's 84 and 85 May 26 and June 3, 1922
Oak tree for corner

Ralph A. Smith R.L.S. #3421
Book 84A Page 3 Witness Book Number 2 Page 83
Found Splice Plate
10" White Oak Southeast 70.0' #3
14" White Oak S85°±W 42.7' #4
12" White Oak West 42.9' #5
10" White Oak S30°E 47.1' #6

Patrick A. Salisbury R.L.S. #13594
Drawing Number 73195AC December 31, 1973
Found ¾" Pipe
18" White Oak West 42.45' #5
16" White Oak S40°E 46.70' #6
7"-6" Clump Maples S85°E 75.0' #7

Paul E. VanKooten R.L.S. #8618
LCRC #517 April 4, 1980 Found 1" Iron
14" Oak East Northeast 64.38' #8
8" Oak West 31.45' #9
18" Oak South Southeast 47.52' #6
Capped Iron (Blass) West 33.0' #10

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found ¾" Pipe, 2½" X 1.8' Angle iron, License plate (1939), White crockery, Green glass, Clear glass (bottle) on woods line going East and the centerline of North and South road is 2.5 feet West and the condition of the recorded witnesses are: #1 thru #3 gone, #4 and #5 Stump, #6 thru #9 good condition, #10 gone.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed ¾" Pipe, 2½" X 1.8' Angle iron and License plate and set a 4" diameter Harrison cast Iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

Oak Stump S85°W 42.71' #4
24" White Oak Stump West 42.32' Face #5
10" White Oak S30°E 47.52' Set spike and tag in Southwest side of tree. #6
7"-6" Clump Maples S85°E 75.35' Set spike and tag in North side of tree. #7
14" Oak N74°E 64.21' Set spike and tag in Northwest side of tree. #8
16" White Oak West 31.48' Set spike and tag in North side of tree. #9

Signed by Norman L. Ochs

Date October 17, 1996

Surveyor's Michigan License No. 22439

Approved by Peer Review Group On December 11, 1996
Norman L. Ochs, County Representative.

Form approved by Michigan State Board of Land Surveyors Jan 30, 1971
Revised May 14, 1975
Revised Jan., 1983



N.L.O.