

1993 NEWAYGO COUNTY REMONUMENTATION PROJECT

NEWAYGO COUNTY  
DEEDS  
MAR 1993

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

94 JAN 21 PM 3 28

For corners in

NEWAYGO

(County)

Located In:

Corner Code #

1. Public Land Survey

T 16N R 12W

A-3

T R

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

VOL 001 PAGE 66

Register of Deeds Stamp & File Number

I, Norman L. Ochs, in a field survey on November 8, 1993

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

SW Cor., Sec. 6, Home Twp., Newaygo County, MI

A. Description of original monument and accessories and/or subsequent restoration.

A-3 (Sec. Cor, Secs. 1, 6 7 & 12, SW Cor., Sec. 6, T16N R12W)

G.L.O. 1837 J. Hodgson

16" W. Pine S50°E Blks #1

20" W. Pine N72°E 43 lks #2

1966 R. A. Griffin Set a

5" x 36" conc. mon

T. Pole N40°E 48.03' #6

P.Pole S44°E 28.58' #7

NE Cor. Blk Cabin S74°W 187.10' #8

14" B. Oak N60°W 55.55' #4

6" W. Oak N33°W 125.03' #9

LCRC #186

NCRC Monument - 1" Pipe

10" W. Oak N60°E 59.0 lks #3

17" R. Oak N60°W 55.1 lk. #4

P.Pole S50°E 28.2 lks #5

1990 Mid-Mich & Eng.

1" Pipe

10 W. Oak N60°E 59.00' #3

17" R. Oak N60°W 55.10 #4

P.Pole S50E 28.20' #5

LCRC #959

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Sept. 22, 1966 Robert A. Griffin RLS #13584

Found 1" iron pipe at the intersection of earth roads North and East.

Length set to project 1.5 feet below ground. A 3" diameter brass disk is cast flush with the top of this monument.

Found R. A. Griffin's conc. mon. in good condition.

Condition of recorded witnesses is: #1 gone, #2 gone, #3 good condition, #4 good condition, #5 good condition, #6 gone #7 good condition, #8 gone, #9 good condition.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted R. A. Griffin's conc. monument as a substantial marker for the section corner

and is accepted as a careful and faithful reestablishment of the position of the original corner

P.Pole S44°E 28.59' (Spike in SW side of Pole) #7

16" W. Oak N65°E 59.41' (Spike in NW side of tree) #3

10" W. Oak N33°W 125.11' (Spike in NE side of tree) #9

20" B. Oak N60°W 55.55' (Spike in South side of tree) #4

Signed by

Norman L. Ochs

Date

November 8, 1993

Surveyor's Michigan License No.

22439

Approved by Peer Review Group Nov. 9, 1993

Norman L. Ochs, County Representative

